




3D Printer Instruction



Please check the file FAQ in you have any question during printing.

Skype: ghj205

Tech Support: hic_technology@outlook.com

Instructional Videos: https://www.youtube.com/channel/UC9Udtwu2QGX6iml-meV6s_w

Catalogue

Inspection.....	1
Y Axes Assembly	2
Z Axes Frame Assembly.....	26
X Axes Assembly.....	40
Z Axes Assembly.....	47
X Axes Motor Belt Assembly.....	56
Hot bed Assembly.....	62
Extruder Assembly.....	67
Control Board Assembly.....	75
Power Supply Assembly	77
LCD Assembly	80
Z Axes Endstop Assembly	83
Filament Holder Assembly	86
Wiring Instruction	90

Checking package after opening



Y Axes Assembly

Attention:



1. Y axes belt clip must be fixed, not allowed loosen
2. Y axes belt pulley must be fixed, belt must be tight enough.
3. Make sure the base board moves smoothly when power off, otherwise it will cause Y axes losing step.

Step 1


Screw specification

1.M5*8

2.M5 nut




410mm aluminum frame



308mm aluminum frame

Make sure the four
angles fixed firmly



alignment



alignment



alignment



6

alignment



alignment




alignment




Pay attention to the screw's direction after it is locked

correct





8




wrong

Step 2

foundation 4pcs
M5*12 4pcs
M5 nut 4pcs




Step 3





M5*12 2pcs
M5 nut 2pcs
2 groups in total

Notice the direction



M5*12 2pcs
M5 nut 2 pcs
2 groups in total




Notice the direction

Step 4



Pay attention
to directions

There are
four places



Step 5

8*410mm polished rod
2pcs
Box type linear bearing
3pcs





Step 6

M3*20
M3 nut



4pcs
4pcs

There are four places




Step 7


M3*16 2pcs
M3 nut 2pcs



Step 8




M8*30	1pcs
M8 nut	1pcs
M5*12	2pcs
M5 nut	2pcs
608 bearing	1pcs



16



Step 9

it is generally in the middle position,
and it needn't lock at first.
While fixing the belt,
it will be locked after some adjustment.





Step 10

M5*8 2pcs
M5 nut 2pcs




Step 11





Step 12

40mm motor 1pcs
M3*5 4pcs



Step 13




Synchronous belt
pulley 1pcs



About
3mm



Step 14

Endstop	1pcs
M2*16	2pcs
M2 nut	2pcs





Step 15

M3*10 2pcs
M3 nut 2pcs



Step 16

M4*8 12pcs




Pushing the acrylic base board by manual backwards and forwards when building machine, fix all screws after it moves smoothly. You can adjust the acrylic parts' left and right position, which fix the polished rods when necessary.

Step 17

Synchronous belt is about 820mm.

The belt installation method is described in the belt installation section (please refer to that section)

https://www.youtube.com/channel/UC9Udtwu2QGX6iml-meV6s_w





Z Axes Frame Assembly

Attention:

Aluminum Frame must be fixed well, not declining or loosen, otherwise, it will cause Z axes stuck.


Step 18

M5*8 4pcs
M5 nut 4pcs




Step 19

295mm long
aluminum frame




About 165mm




Step 20

M5*8 2pcs
M5 nut 2pcs

410mm long
aluminum frame




51mm




Step 21

M5*8 2pcs
M5 nut 2pcs

295mm long
aluminum frame





51mm




Step 22


M5*8 4pcs
M5 nut 4pcs



Step 23





165mm



Step 24

M5*8 2pcs
M5 nut 2pcs



Pay attention to
the direction



Step 25



M5*8 2pcs
M5 nut 2pcs

Pay attention
to direction



Step 26


Alignment



35

Step 27



Alignment



Step 28


M3*5 4pcs
34mm motor 1pcs

34mm long




For your attention:
please find that the
motor terminal
faces backwards

Wire
connection
port



Step 29




M3*5 4pcs
34mm motor 1pcs



For your
attention: please
find that the
motor terminal
faces backwards

Step 30



Coupling 2pcs



X Axes Assembly



Step 31

M8 nut	1pcs
M3*16	2pcs
M3 nut	2pcs




Step 32

Endstop	1pcs
M2*16	2pcs
M2 nut	2pcs




Step 33

M8 nut	1pcs
M3*16	2pcs
M3 nut	2pcs



Step 34



Bearing	2pcs
M3*20	1pcs
M3 nut	1pcs
M3 filler piece	2pcs



For your attention, M3 screw cannot be fix too tight, making sure the bearings turns smoothly

Step 35



8*410
polished rod
2 pcs



Step 36

Box type liner bearing 3pcs

Polished rods are align with printed part



Z axes Assembly



Attention:

1. Make sure X axes moves smoothly before assembling Z axes screw rods.
2. Make sure X axes is level, not gradient when you assemble screw rods. Otherwise, the Z axes will be stuck.
3. The screw must be fixed on the coupling, otherwise, the X axes will be gradient and Z axes stuck.
4. After finishing assembly, please rotate the screw rods to the same direction by hands, make sure they move smoothly, no stuck, then power it and adjust.

Step 37

M5*12 2pcs
M5 nut 2pcs



Pay attention
to the direction



Step 38



M5*12 2pcs
M5 nut 2pcs

Pay attention
to the
direction





Step 39

Pay attention to the direction






Step 40

Pay attention to
the direction



Step 41

320mm polished
rod 2pcs



For your attention: Polished rods must insert into the metal hole after it through the bearings from up to down. Pushing X axes by manual from up to down to make sure it moves smoothly, if it doesn't, you can adjust the left and right printed parts distance of X axes.

Step 42


M3*20

2pcs

M3 nut



2pcs

2 positions




Step 43

M8 screw rod
2pcs



Clockwise insert
two screw rods
from up and down
at the same time

Step 44



After insert the two screw rods into the coupling, Fix the coupling side screws in condition of making sure X axes is entirely level.



X Axes Motor Belt Assembly & Bed Auto Leveling

Attention:

1. Belt pulley must be fixed.
 2. Bearings in right hand must rotate smoothly.
 3. Belt must be tight .
 4. Push the metal part from left to right and move smoothly when power off.
- Otherwise, the X axes will lose step when printing


Step 45

M3*12 2pcs



Step 46

M4*8 10pcs





Moving to right and left smoothly

making sure the whole kit moves smoothly after screws fixed

Step 47

40mm motor 1pc
M3*20 3pc




For your attention:
please find
that the motor
terminal
faces
downwards


Step 48

M4*8

2pcs





Bed Auto Leveling-1



Step 49



SN40-N Endstop 1pcs
M3*20 2pcs
M3 filler piece 2pcs

Bed Auto Leveling-2




Step 50

Synchronous belt
pulley 1pcs




2mm



Step 51



Synchronous belt is about 850mm ,
The belt installation method is described in the belt installation section
(please refer to that section).




Hot bed Assembly

Step 52

M3*25 flat head screw 2pcs
Diameter 6mm spring 2pcs



Step 53





The two screws are inserted into the metal plate holes individually

Step 54

M3*25 flate head screw 2pcs
Diameter 6mm spring 2pcs



Installing two springs to other side of bed, insert the screws into the acrylic holes



Step 55

Hand nut 4pcs

4 position





Extruder Assembly

Attention:

1. Make sure the V bearing can stick on the filament gear under the pressure of Spring.
2. Make sure the filament can be inserted from feed port into throat nozzle, otherwise, it will cause extruding filament abnormally or don't extrude filament.

Step 56

M6*8 1pcs






68

Step 57

40mm motor 1pcs
M3*5 1pcs



For your attention:
please
find that the
motor termin-
-al faces upwards



Filament hole is about in
the middle of extrusion
pulley.


Step 58

M3*16 flat headed screw
1pcs





Step 59

Diameter 8mm spring 1pcs





Step 60

M3*5screw 1 pcs





Step 61

- | | |
|------------------|------|
| Heat sink | 1pcs |
| 4010 fan | 1pcs |
| Fan net | 1pcs |
| Isolation pillar | 2pcs |
| M3*45 | 2pcs |
| M3 filler piece | 2pcs |



Step 62

Turbine fan 1pcs
M3*20 2pcs





Control Board Assembly

Step 63

M3*5 4pcs

Pay attention to the control board direction, Printing interface is on the upper left.




Power Supply Assembly

Step 64



M3*5 4pcs

Pay attention to the power supply terminal faces downwards



Step 65



M5*8 2pcs
M5 2pcs



LCD Assembly

Pay Attention to Connection Of LCD and Control Board (Refer to picture on final page)



Step 66



81

Step 67

M3*5 4pcs





82

Filament Holder Assembly



Step 68

M5*8 2pcs
M5 nut 2pcs

2 groups in total




Step 69



Each one
at left and
right hand


Step 70






Wiring Instruction

Attention:

When you are wiring, must distinguish the positive and negative pole and make sure connecting position correct. otherwise, it will cause abnormal or defective. If you have any quesitons, please contact us firstly !







+V on power supply connects to + on upper left corner of control board.

COM connects to - on upper left corner of control board.

Attention: If the + and - are connected contrary, the board will be defective



Thanks for watching!
We are trying our best to keep improving
If any question or suggestion,
Welcome to contact us at
info@ljelectronic.com
www.hic3dprinter.com

Tech Support: hic_technology@outlook.com
Instructional Videos: https://www.youtube.com/channel/UC9Udtwu2QGX6iml-meV6s_w