

TRADE TRAINING II-III TTC PROGRAMME



TURNER























GOVERNMENT OF THE PUNJAB
TECHNICAL EDUCATION & VOCATIONAL TRAINING AUTHORITY
TRADE TESTING BOARD
DEVELOPMENT CELL LAHORE



T.T.P. Series No.25

Price Rs.45.00

			
Longitudinal turning 1	Turning between Centres 2 → 4.2.2/2	Drilling, Reaming 3 → 13	Drilling, Grooving 4
			
Longitudinal and Taper turning 5 → 4.2.1/9	Internal turning 6	Thread cutting 7	Turning of Brass 8
			
Thread cutting 9	Stepturning 10	Thread cutting 11	Fitting 12
			
Internal taper turning 3 → 13	Knurling, Longitudinal turning 14 → 4.2.2/5	Internal & External thread cutting 15	Thread cutting, Work with steadyrest 16 → 3.3.1/2
			
Bush fitting 17	Left hand thread cutting 2.3.6/5 → 18 → 3.3.1/2	Internal Acme thread cutting 3.2.1/3 → 19 → 3.3.1/2	Test piece 20 → 4.3.2/1

In addition to the exercises shown above, the trainees have to make parts which are needed for the training centre.

TRADE
TRAINING II

LAYOUT

MP/2.1/3.11

TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

MATERIAL REQUIRED

TURNER

TRADE TRAINING II

TURNING II

NO.3.1.1./1to20

Exercise No	Length given in Millimeter										Length per trainee	Total Length for 16 trainees	Total weight for 16 trainees			
	1	2.1	2.2	2.3	2.4	2.5	3	4	5	6				7.1	7.2	7.3
MILDSTEEL ϕ 38mm 1 1/2" DIA	156													156 mm	2.5 meter	22.25kg
CARBON STEEL ϕ 22mm 7/8" DIA	156													156 //	FOR 4 Trainees	1.9 //
CARBON STEEL ϕ 26 mm 1 1/16" DIA		156	156	156										468 //	FOR 9 Trainees	18.9 //
CARBON STEEL ϕ 29mm 1 1/8" DIA					156									156 //	FOR 3 Trainees	2.6 //
MILDSTEEL ϕ 50mm 2" DIA						60								60 //	0.96 //	11.4 //
CASTIRON ϕ 88mm (Block) 3 1/2" DIA							45							45 //	0.72 //	CAST IRON AS PER PATTERN.
HIGH SP. STEEL ϕ 19mm 3/4" DIA								220						220 //	3.5 //	9.3 kg
MILDSTEEL SQUARE 44x44mm 13/4" x 1 3/4"									45					45 //	0.72 //	10 //
8 M.S. PIPE ϕ 16mm 5/8" DIA										101				101 //	1.6 //	Running meas. 1.7 meter
M.S. ROUND ϕ 30mm 1 1/4" DIA											50			50 //	0.8 //	4.4 kg
M.S. ROUND ϕ 44mm 1 3/4" DIA												16		16 //	0.26 //	2.8 //

Continued



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

MATERIAL REQUIRED

TURNER

TRADE TRAINING II

TURNING II


No.3.1.1/8to13

Exercise No. (Length given in millimeter)

	Exercise No. (Length given in millimeter)													Length per trainee	Total length for 16 trainees	Total weight for 16 trainees	
	8.1	8.2	8.3	9.1	9.2	10	11.1	11.2	11.3	12.1	12.2	13.1	13.2				
BRASS ϕ 16mm 5/8" DIA	56														56 mm	0.9meter	1.42 kg
BRASS ϕ 25mm 1" DIA		21													21 mm	0.34meter	1.36 kg
BRASS ϕ 14mm 9/16" DIA			81												81 mm	1.3meter	1.57 kg
MILD STEEL ϕ 32 mm 1 1/4" DIA									35						147mm	2.35meter	14.83kg
M.S. ϕ 51mm 2" DIA					56	56									171mm	2.74meter	43.6 kg
M.S. ϕ 38mm 1 1/2" DIA						63	26								31 mm	0.5 meter	4.45 kg
M.S. ϕ 28mm 1 1/8" DIA															122mm	2meter	9.66 kg

Continued





Exercise No	ϕA	ϕB	C	Marks given
1.1	$36 \pm 0,2$	$30 \pm 0,2$	$50 \pm 0,2$	
1.2	$32 \pm 0,1$	$26 \pm 0,1$	$52 \pm 0,1$	
1.3	$30 \pm 0,1$	$24 \pm 0,1$	$54 \pm 0,1$	
1.4	$26 - 0,1$	$21 - 0,1$	$56 - 0,1$	

SCALE 1:1

MAT: MILDSTEEL

MEASURING EXERCISE

MP/23/ 3.1.1/1

TURNING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

FOR ALL DIMENSIONS ± 0.1
UNLESS OTHERWISE STATED



Grinding ϕ	ϕ A	ϕ B	C
ϕ 20	20 , 5	17	15
ϕ 21	21 , 5	18	16
ϕ 22	22 , 5	19	17
ϕ 23	23 , 5	20	18
ϕ 24	24 , 5	20	18

SCALE 1:1

MAT. CARBON ST.

Mandrel

MP/2.3/3.1.1/2


TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $54 \begin{smallmatrix} + \\ - \end{smallmatrix} 0.1$
2. $\varnothing 48 \begin{smallmatrix} + \\ - \end{smallmatrix} 0.1$
3. $\varnothing 42 - 0.1$
4. $\varnothing 42 - 0.1$
5. $\varnothing 28 + 0.1$
6. $26 + 0.1$
7. $18 + 0.1$
8. $10 + 0.1$
9. Smoothness of bore
10. Smoothness all over

The shoulder in the bore must be in right angle !

SCALE 1:1

BUSH

MP/23/ 3.1.1/ 3

MAT: MILDSTEEL


TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


TURNER




CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $\phi 68 - 0.1$
2. $\phi 42 - 0.1$
3. $\phi 40 + 0.1$
4. $\phi 32 + 0.1$
5. 40 ± 0.1
6. $16 - 0.1$
7. $8 + 0.1$
8. $16 - 0.1$
9. $10 + 0.1$
10. Smoothness all over

Mind the hard casting skin when you choose the depth of the first cut !

SCALE 1:1	PULLEY	MPI/2.3/3.1.1/4
MAT. CAST IRON		TURNING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER




CHECK THE FOLLOWING POINTS VERY CAREFULLY

- 1. \emptyset 16.4
- 2. \emptyset 18.2
- 3. 125
- 4. 80
- 5. 14

Use the Taper gauge to check the taper Morse No. 2


SCALE 1:1	DRILL BODY	MP/2.3/ 3.1.1/5
MAT. HIGH SP. ST.		TURNING II
DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER




CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $\varnothing 35 + 0.1$
2. $\varnothing 25 + 0.1$
3. $\varnothing 15 + 0.1$
4. $13.5 + 0.1$
5. $9.0 + 0.1$
6. $4.5 + 0.1$
7. Smoothness of stepped hole 35 mm
8. Smoothness of stepped hole 25 mm
9. Smoothness of stepped hole 15 mm
10. Smoothness all over

Use a suitable filling disc when chucking the ready machine side !

SCALE 1:1	PAPER WEIGHT	MP/23/ 3.11/6
MAT: MILDSTEEL		TURNING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME	TURNER	

TOLERANCE $\pm 1/64''$




CHECK THE FOLLOWING POINTS VERY CAREFULLY

- | | | | |
|---------------------------------------|-------------------|---|-----------------|
| 1. Smoothness pipe thread | R 1/2 " x 1 3/4 " | - | Piece No. 1 |
| 2. Smoothness pipe thread | R 1/2 " x 5/8 " | - | Piece No. 1 |
| 3. Smoothness drilled hole | Ø 5/8 " | - | Piece No. 1 |
| 4. Smoothness pipe thread | R 1/2 " x 1 3/4 " | - | Piece No. 2 |
| 5. Smoothness outside diameter | 1 1/16" x 1 3/4 " | - | Piece No. 2 |
| 6. Accuracy of pipe thread connection | R 1/2 " | - | Piece No. 1 + 2 |
| 7. Smoothness pipe thread | R 1/2 " x 3/8 " | - | Piece No. 3 |
| 8. Smoothness of faces | - | - | Piece No. 3 |
| 9. Accuracy of pipe thread connection | R 1/2 " | - | Piece No. 1 + 3 |
| 10. Smoothness and accuracy all over | - | - | Piece No. 1 + 3 |

Prepare parts 2 and 3 first and check part 1 with their help !

SCALE 1:1	PIPE LONG - THREADING	MP/2-3/ 3.1.1/7
MAT: MILDSTEEL		TURNING II



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. 50 ± 0.1 - Piece No. 1
2. ϕ 14.7 - 0.1 - Piece No. 1
3. ϕ 12.2 - 0.1 - Piece No. 1
4. 16 - 0.1 - Piece No. 2
5. ϕ 22 - 0.1 - Piece No. 2
6. ϕ 12.8 + 0.1 - Piece No. 2
7. 38 - 0.1 - Piece No. 3
8. 38 - 0.1 - Piece No. 3
9. ϕ 12 - 0.1 - Piece No. 3
10. Smoothness all over- Piece No. 1 - 3

Mind that the cutting angles for brass differ from those for steel !

SCALE 1:1

MAT BRASS

RUBBER PIPE CONNECTION

MP/2.3/3.1.1/8


TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



CHECK THE FOLLOWING POINTS VERY CAREFULLY

- | | | |
|----------------------------------|---------------|-------------------|
| 1. Smoothness pipe thread | R 1/2" x 7/8" | - Piece No. 1 |
| 2. Smoothness pipe thread | R 1/2" x 5/8" | - Piece No. 1 |
| 3. Smoothness drilled hole | Ø 1/4" | - Piece No. 1 |
| 4. Smoothness of faces | | - Piece No. 1 |
| 5. Smoothness pipe thread | R 1/2" x 7/8" | - Piece No. 2 |
| 6. Smoothness pipe thread | R 1/2" x 3/4" | - Piece No. 2 |
| 7. Smoothness outside diameter | 1 1/8" | - Piece No. 2 |
| 8. Smoothness of face and radius | | - Piece No. 2 |
| 9. Accuracy of connection | R 1/2" right | - Piece No. 1 + 2 |
| 10. Accuracy of connection | R 1/2" left | - Piece No. 1 + 2 |

Mind the left hand and right hand threads on both workpieces !

SCALE 1:1

MAT. MILDSTEEL

DOUBLE NIPPLE AND SOCKET

MP/23/ 3.1.1/9

TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Tolerance $\pm 0,1$
unless otherwise stated

16



SEQUENCE OF OPERATION

1. Clamp the workpiece in the chuck, drill and bore (ream) the holes 18H7 and $\phi 30 + 0.02$. Prepare the internal recess $\phi 36$.
2. Turn the diameter $48 - 0.05$ roughly (48.5).
3. Clamp on rough turned diameter 48.5 and check for true running, then bore $\phi 26 + 0.2$.
4. Hold the workpiece on a mandrel and finish the outside diameters and grooves according to the drawing.

Check the recess in the bore with spring caliper.

SCALE 1:1

MAT. MILD STEEL

STEPPED BUSH

MP/2.3/3.1.1/10


TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



CHECK THE FOLLOWING POINTS VERY CAREFULLY

- | | | |
|-----|------------------------------------|-------------------|
| 1. | 55 - 0.1 | - Piece No. 1 |
| 2. | 51 + 0.1 | - Piece No. 1 |
| 3. | ϕ 25 - 0.1 | - Piece No. 1 |
| 4. | ϕ 15 \pm 0.03 | - Piece No. 1 |
| 5. | 55 - 0.1 | - Piece No. 2 |
| 6. | ϕ 25 - 0.1 | - Piece No. 2 |
| 7. | ϕ 15 \pm 0.03 | - Piece No. 2 |
| 8. | Accuracy and smoothness of notches | - Piece No. 2 |
| 9. | Accuracy of bolt connection | - Piece No. 1 + 2 |
| 10. | Smoothness all over | - Piece No. 1 + 2 |

Check the compression of the unit by closing the ϕ 5 mm hole with the finger-tip !

SCALE:1:1

PLUNGER AND ZYLINDER

MP/23/ 3.1.1/12

MAT:MILDSTEEL

TURNING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TOLERANCE ± 0.2

∇ ($\nabla\nabla$)




CHECK THE FOLLOWING POINTS VERY CAREFULLY

- | | | |
|-----|---|-----------------|
| 1. | 50 ± 0.1 | - Piece No. 1 |
| 2. | $\phi 47 \pm 0.1$ | - Piece No. 1 |
| 3. | $\phi 40 \pm 0.1$ | - Piece No. 1 |
| 4. | $\phi 24 + 0.05$ | - Piece No. 1 |
| 5. | Accuracy of fine pitch thread M 38 x 1.5- | Piece No. 1 |
| 6. | Accuracy of taper 1 : 5 | - Piece No. 1 |
| 7. | Smoothness all over | - Piece No. 1 |
| 8. | Accuracy of fine pitch thread M 38 x 1.5- | Piece No. 2 |
| 9. | Accuracy and smoothness all over | - Piece No. 2 |
| 10. | Accuracy of thread connection M 38 x 1.5- | Piece No. 1 + 2 |

Check the taper with a taper gauge !

SCALE 1:1	TAPERBUSH WITH RINGNUT	MP/2.3/3.1.1/13
MAT: MILDSTEEL	FROM EX.3	TURNING II
DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER



Material: Mild-steel

CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. 90 ± 0.1
2. 30 - 0.1
3. 30 - 0.1
4. 20 - 0.1
5. 20 - 0.1
6. Accuracy of fine pitch thread M 27 x 1.5
7. Thread fit M 27 x 1.5
8. Accuracy of metric-thread M 27
9. Thread fit M 27
10. Smoothness all over

- Piece No. 1
- Piece No. 1
- Piece No. 1
- Piece No. 2
- Piece No. 3
- Piece No. 1 + 2
- Piece No. 1 + 2
- Piece No. 1 + 3
- Piece No. 1 + 3
- Piece No. 1 - 3

Find out the pitch of M 27 from the table book !

SCALE
MAT. MILD STEEL

SCREW FITTING


MP/2.3/3.1.1/15
TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING
PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

30_{h6} ± 0.033
± 0.017



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $\phi 16$
2. $\phi 14 - 0.2$

Before starting thread cutting check the pitch.

The raw piece is to be cut to a length of about 335 mm so that a centre bore can be made as shown in the detail to allow the use of a tailstock centre. After completing all operations (thread cutting) the spindle is to be clamped with the thread in a collet chuck or with the head in the three jaw chuck and the $\phi 12$ in the steady rest to allow completion of the 120° end.

SCALE 1:1

MAT: MILDSTEEL

SPINDLE

MP/23/ 3.1.1/16

TURNING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

TOLERANCE FOR ALL DIM.±0.1
UNLESS OTHERWISE STATED



SCALE 1:1
MAT.MILDSTEEL



BUSH FITTING

MP/2-3/ 3.11/ 17
TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING
PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SCALE 1:1	SCREW SOCKET AND NUT :FROM 2.3.6/5	MP/23/3.1.1/18
MAT: MILDSTEEL		TURNING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING
PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

25



TOLERANCE ± 0.1 UNLESS
OTHERWISE STATED



SEQUENCE OF OPERATION

1. Mount four jaws chuck on Lathe Machine.
2. Hold finished milled workpiece in four jaws chuck and check true running.
3. Bore core diameter for Acme thread 27 x 3.
4. Cut left hand Acme thread.

CAUTION

Check the thread with the male piece.

SCALE 1:1

MAT: MILDSTEEL

LINK PIECE

FROM 3.21/3

MP/2.3/ 3.1.1/19

TURNING II








DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance ± 0.1



Material : Mild-steel
Brass

SCALE 1:1

SPINDLE AND THREAD BUSH

MP/2.3/ 3.1.1/ 20

MAT:













TURNING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

		
<p>Parallel and right angle shaping 1 — 2 —> 5</p>	<p>Shaping of Cast iron 3 —> 4.1/6</p>	<p>Step shaping 4 —> 4.1/8</p>
		
<p>Shaping of grooves 1 —> 5 —> 6</p>	<p>Angular shaping 5 —> 6 —> 3.2.4/8</p>	<p>Rack shaping 7</p>
		
<p>Dove tail shaping, external 8</p>	<p>Dove tail shaping internal 9</p>	<p>Form shaping 10 —> 4.1.2/5</p>
		
<p>Step shaping 11</p>	<p>Internal form shaping 12</p>	<p>External form shaping 13</p>

In addition to the exercises shown above, the trainees have to make parts which are needed for the training centre.

TRADE
TRAINING II

LAYOUT

MP/2.1/3.1.2

SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

MATERIAL REQUIRED

TRADE TRAINING II

TURNER

SHAPING II

NO.3.1.2/1 to 13


Exercise No. (Length given in Millimeter)

	Exercise No. (Length given in Millimeter)													Total Length for 16 trainees	Total weight for 16 trainees	
	1	2	3	4	7	8	9	10	11	12	13					
M.S. SQUARE 44x44mm 1 3/4" x 1 3/4" sq.	76	46											116	238 mm	3.8 meter	58.5 kg
CAST IRON 96x30mm 3 3/4" x 1 1/4"			106											106 "	17 "	37.0 "
CAST IRON 76x42 mm 3" x 1 3/4"				120										120 "	2 "	48.0 "
CAST IRON SQ. 44x44mm 1 3/4" x 1 3/4" sq.					156									156 "	2.5 "	36.0 "
M.S. SQ. 62x62 mm 2 1/2" x 2 1/2" sq.						26	26							52 "	0.84 "	25.5 "
CAST IRON 81x76mm 3 1/4" x 3"									156					156 "	2.5 "	114.0 "
M.S. SQUARE 75x75mm 3" x 3" sq.												25	25	50 "	0.8 "	35.5 "



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. 40 ± 0.1
2. 40 ± 0.1
3. 70 ± 0.1
4. Angle A - B
5. Angle C - D
6. Angle A B C D - E
7. Angle A B C D - F
8. Parallel surface
9. Plane surface
10. Smoothness all over

Use parallel distance pieces to chuck the job
in the vice !

SCALE 1:1

MAT: MILD STEEL

V - BLOCK

MP/23/31.2/1


SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


TURNER




CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $40.2 + 0.1$
2. $40.2 + 0.1$
3. $40.2 + 0.1$
4. Angle A - B
5. Angle C - D
6. Angle A B C D - E
7. Angle A B C D - F
8. Parallel surface
9. Plane surface
10. Smoothness all over

First shape two opposite surfaces parallel with each other !

SCALE 1:1	CUBE	MP/23/31.2/2
MAT: Mildsteel		SHAPING II
	DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING	TURNER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. Angles
2. Parallel surfaces
3. Plane surfaces
4. Smoothness all over

Mind the hard casting skin when you choose the depth of the first cut !

SCALE 1:1

MAT: CAST IRON

ECCENTRIC BORING PLATE

MP/23/ 3.1:2/3


SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME


TURNER




CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. 70 - 0.1
2. 66 - 0.1
3. 36 + 0.1
4. 30 - 0.1
5. 30 - 0.1
6. 30 - 0.1
7. 30 - 0.1
8. Angle surface
9. Parallel surface
10. Smoothness all over

Machining of cast iron does not require any cooling liquid !

SCALE 1:1	MOVEABLE NUT	MP/ 23/ 3.1.2/4
MAT: CAST IRON		SHAPING II
	DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING	TURNER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		

Tolerance ± 0.1
unless otherwise stated



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $18 - 0.1$
2. $17 - 0.1$
3. $16 - 0.1$
4. $19 + 0.1$
5. $12 + 0.1$
6. 8 ± 0.1
7. 8 ± 0.1
8. Notches, parallel and rectangular
9. Notches, smoothness
10. Smoothness all over

Grind the slotting tool to 4 mm width to shape the 4 mm slot !

SCALE 1:1

MAT.: MILDSTEEL

Mat. from Ex 1

V-BLOCK

MP/ 23/ 3.1.2/5

SHAPING II





DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance ± 0.2
unless otherwise stated



CHECK THE FOLLOWING POINTS CAREFULLY

1. 32 ± 0.2
2. 90°
3. 20 ± 0.2
4. Angle 90°
5. Parallel Surfaces
6. Smoothness all over

When checking the 90° angle the edge of the try-square must not touch the bottom of the groove !

SCALE 1:1

MAT.:MILDSTEEL

from Ex.5

V- BLOCK

MP/2.3/3.1.2 / 6


SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER




CHECK THE FOLLOWING POINTS VERY CAREFULLY


Modul : 3

1. 150 - 0.1
2. 38 - 0.1
3. 38 - 0.1
4. 6.5 - 0.1
5. 6.5 - 0.1
6. Accuracy of angle 60°
7. Dimensional accuracy of teeth 90°
8. Dimensional accuracy of teeth 60°
9. Angle and parallel surface
10. Smoothness all over

All teeth must be precisely parallel !

SCALE 1:1	RACK	MP/2.3/3.1.2/7
MAT: CAST IRON		SHAPING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

Tolerance $\pm 30'$



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $60 - 0.1$
2. $60 - 0.1$
3. $50.3 - 0.1$
4. $20 - 0.1$
5. 10 ± 0.1
6. 10 ± 0.1
7. Angle 60°
8. Angle 60°
9. Angle and parallel surface
10. Smoothness all over

Debur carefully after shaping !

SCALE 1:1

DOVE TAIL

MP/23/3.1.2/8

MAT.: MILDSTEEL

SHAPING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance $\pm 30'$



CHECK THE FOLLOWING POINTS VERY CAREFULLY

1. $60 - 0.1$
2. $60 - 0.1$
3. $16.1 + 0.1$
4. $40 + 0.1$
5. $20 - 0.1$
6. 10 ± 0.1
7. Angle 60°
8. Angle 60°
9. Angle and parallel surface
10. Smoothness all over

Check the dove tail with the matching piece shown in drawing no. 8 !

SCALE 1:1

MAT: MILDSTEEL

DOVE TAIL

MP/2.3/3.1.2/9


SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER




SEQUENCE OF OPERATION

1. Shape the base surface and recess 70 x 4.
2. Use this face as a reference to shape the width 70.
3. Shape to length 150.
4. Shape radius 35 mm and thickness 19 mm.
5. Chamfer 3 x 45°.

SCALE 1:1	BRACKET	MP/2.3/3.1.2/10
MAT. CAST-IRON		SHAPING II
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

Tolerance ± 0.1



SCALE 1:1

MAT.MILD STEEL

CLAMPING TOOL

MP/2.3/3.1.2/11



SHAPING II



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING




PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



1

2



SCALE 1:1

MAT: MILDSTEEL

TONGUE FITTING

MP/ 23/ 3.1.2/12-13
















SHAPING II




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

 Longitudinal turning 1 → 4.2.2/1	 Turning between centres 2 → 4.2.2/	 Double start thread cutting 3
 Thread cutting 4 → 4.3.2/2	 Knurling, Boring 5 → 4.3.2/2	 Eccentric boring 3.1.2/3 → 6
 Eccentric turning 7	 Working on a four jaw chuck 3.1.2/4 → 8	 Working on a Mandrel 9
 Eccentric turning 10 → 4.2.2/8	 Exercising of known operations 11	 Exercising of known operations 12
 Form turning 13	 Assembling 14	 Exercising of known operations 15

In addition to the exercises shown above, the trainees have to make parts which are needed for the training centre.

TRADE TRAINING III	LAYOUT	MP/2.1/4.1.1
		TURNING III
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

MATERIAL REQUIRED
TURNER

TRADE TRAINING III
TURNING III

No.4.1.1/1 to 15

Exercise No. (Length given in Millimeter)

Exercise No.	(Length given in Millimeter)										Length per Strainee	Total length for 16 Trainees	Total weight for 16 Trainees			
	1.1	1.2	1.3	1.4	2.1	2.2	2.3	2.4	2.5	3.1				3.2	4.1	4.4
156														156 mm	2.5 meter	30.6 kg
156 156														312 mm	5 meter	44.5 kg
			156							307				468 mm	7.5meter	47.3 kg
					136	136	136							408 mm	6.53meter	14.56 kg
						136	136							272 mm	4.35meter	13 kg
								190						190 mm	3 meter	12.5 kg
										38				38 mm	0.29meter	9.6 kg
												28		28 mm	0.45meter	1 kg

continued



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

MATERIAL REQUIRED

TURNER

TRADE TRAINING III


TURNING III

No. 4.1.1/ Exercise No.	(Length given in Millimeter)										Length per Trainee	Total length for 16 Trainees	Total weight for 16 Trainees					
	5.2	5.3	7	9	10	11	12	13	14	14.2				14.3	14.4	15.1	15.2	15.3
M.S.Round Ø70mm (2 3/4" DIA)	56															56 mm	0.9 meter	27.0 kg
M.S.Round Ø63mm (2 1/2" DIA)	54															54 mm	0.86meter	21.3 kg
Cast Iron Ø86mm (3 3/8" DIA)	44															44 mm	0.7 meter	30.0 kg "CASTING"
Cast Iron Ø105mm (4 1/4" DIA)	46															46 mm	0.74meter	26.3 kg "CASTING"
M.S.Round Ø51mm (2" DIA)					142	91										233 mm	3.7 meter	60.0 kg
M.S.Round Ø82mm (3 1/4" DIA)						56										56 mm	0.9 meter	23.5 kg
M.S.Round Ø32mm (1 1/4" DIA)							131									131 mm	2.1 meter	13.3 kg
M.S.Round Ø22mm (7/8" DIA)							81									81 mm	1.3 meter	3.9 kg
M.S.Squ. 25x25mm (1" squ.)								40								40 mm	0.64meter	3.3 kg
M.S.Round Ø82mm (3 1/4" DIA)									36							36 mm	0.58meter	23.2 kg
M.S.Round Ø63mm (2 1/2" DIA)									22							22 mm	0.35meter	8.75 kg
M.S.Round Ø25mm (1" DIA)												84				84 mm	1.34 meter	5.4 kg
M.S.Round Ø32mm (1 1/4" DIA)											21					45 mm	0.72meter	4.55 kg
M.S.Round Ø50mm (2" DIA)													75			75 mm	1.2 meter	19.0 kg
M.S.Round Ø44mm (1 3/4" DIA)														35		35 mm	0.56meter	6.74 kg




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME




Exercise No	ϕA	ϕB	C	Marks given
1.1	$38 \pm 0,03$	$34 \pm 0,03$	$40 \pm 0,1$	
1.2	$36 \pm 0,02$	$32 \pm 0,02$	$42 \pm 0,1$	
1.3	$33 \pm 0,02$	$29 \pm 0,02$	$44 \pm 0,1$	
1.4	$30 \pm 0,01$	$27 \pm 0,01$	$46 \pm 0,1$	

Diameters must be checked with the Micrometer 25 to 50 mm.

SCALE 1:1	MEASURING EXERCISE	MP/23/4.11/ 1'
MAT: MILDSTEEL		TURNING III
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

TOLERANCE ± 0.1

46



Grinding \varnothing	\varnothing A	\varnothing B	C
\varnothing 15	15,2	13	12
\varnothing 16	16,2	14	12,5
\varnothing 17	17,2	14,5	13
\varnothing 18	18,2	15	13
\varnothing 19	19,2	16	14

SCALE 1:1

MAT.CARBON ST.

Mandrel

MP/2.3/4.1/2

TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



TURNER




47

Tolerance $\pm 0,1$
unless otherwise stated

47



Detail A



CUTTING A MULTIPLE THREAD, PROCEED AS IF CUTTING A SINGLE THREAD OF THE REQUIRED LEAD BY USING A TOOL ACCORDING TO THE GIVEN PITCH.

AFTER CUTTING THE FIRST THREAD GROOVE, IT IS NECESSARY TO GIVE THE WORK EXACTLY HALF A TURN WITHOUT TURNING THE LEAD SCREW.

USE THE METHOD TO DISENGAGE THE INTERMEDIATE GEAR FROM THE SCREW GEAR TO MOVE THE LATHE SPINDLE ONE HALF TURN.

SCALE 1:1

MAT. MILD STEEL

SPINDLE AND NUT
(with double thread)

MP/2.3/4.11/3

TURNING III




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME



TURNER

48

FOR ALL DIMENSION ± 0.1
UNLESS OTHERWISE STATED



Acme threads $\phi 26 \times 5$ mm pitch




1	Washer		St 37	5	$\phi 30 \times 3$
1	Hexagon bolt	DIN 558	St 37	4	M8 X 10
1	Spindle		St 37	1	$\phi 30 \times 302$
REQD	NAME	STANDARD	MATERIAL	NO	SIZE

SCALE 1:1	DETAIL OF SUPPORT	MP/2.3/4.1.1/4
MAT.MILD STEEL		TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING
PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Hold the nut by using the ready spindle as a mandrel to turn $\phi 42$ and groove.

1	Head		St 37	3	$\phi 60 \times 50$
1	Nut		St 37	2	$\phi 70 \times 52$
REQD	NAME	STANDARD	MATERIAL	NO	SIZE

SCALE 1:1

MAT: MILDSTEEL

DETAIL OF SUPPORT

MP/2.3/4.1.1/5


TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER




Sequence of Operation

1. Mark and center the workpiece
2. Clamp the workpiece on the face plate
3. Rough the bores
4. When finishing, check the diameter with the internal dial test indicator

SCALE 1:1	ECCENTRIC BORING PLATE	MP/2.3/4.1.1/6
MAT. CAST IRON	<small>From 312/6</small>	TURNING III
DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING		TURNER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		

FOR ALL DIMENSIONS ± 0.1
UNLESS OTHERWISE STATED



SEQUENCE OF OPERATION

1. Hold workpiece in 3-jaw chuck, face and turn outside $\phi 80 \times 21$.
2. Turn step $\phi 70 \times 5$. Re-chuck, face to length 35 mm.
3. Turn step $\phi 70 \times 15$.
4. Mark out excentre 15 mm and centre drill with the help of drilling machine.
5. Mount 4-jaw chuck.
6. Hold workpiece in such a way that the previously drilled centre hole runs true.
7. Turn excentre $\phi 40 \times 10$ and radius 2.
8. Pre-drill and drill $\phi 24.5$
9. Mount boring tool and finish hole to $\phi 25$.

SCALE 1:1

MAT: CAST IRON

ECCENTRIC SHEAVE

MP/23/4.1.17

TURNING III




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance ± 0.1



SEQUENCE OF OPERATION

1. Mark out the centres and drill.
2. Hold in 4-jaw chuck, pre-drill and bore hole $\phi 33$.
3. Hold between centres and turn both sides to $\phi 25_{e8} \times 20$.

25^{e8}	-0.040
	-0.078

SCALE 1:1
MAT: CAST IRON

MOVEABLE NUT
From 31.2/4

MP/2.3/4.1/8
TURNING III




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

▽ (▽▽)

FOR ALL DIMENSIONS ± 0.1
UNLESS OTHERWISE STATED



Turn the outside diameter by using a mandrel to ensure true running.

25	H7	+0.021 0.000
----	----	-----------------

SCALE 1:1
MAT: CAST IRON

PULLEY

MP/2.3/4.1.1/9
TURNING III




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

FOR ALL DIMENSION ± 0.1
UNLESS OTHERWISE STATED



SEQUENCE OF OPERATION

1. Face to the length of 135 mm
2. Mark and drill all 6 centres.
3. All other operations are to be completed with the workpiece held between centres.

$28\phi_{h8}$	0.000 -0.033
$15\phi_{h8}$	0.000 -0.027

SCALE 1:1	CRANK SHAFT	MP/2.3/4.11/10
MAT. MILDSTEEL		TURNING III




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

FOR ALL DIMENSIONS ± 0.1
UNLESS OTHERWISE STATED




SEQUENCE OF OPERATION

1. Turn $\phi 26$ to oversize 27 in the first step.
2. Hold $\phi 27$ in the three jaw chuck and complete knurled and threaded portions of the job.
3. Keep this job till the nut M 24 x 2 is ready as it will be needed for holding the screw during the finishing operations.

SCALE 1:1	MOVEABLE SCREW	MP/2.3/4.1.1/11
MAT: MILDSTEEL		TURNING III
DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER

FOR ALL DIMENSIONS $\pm 0,1$
UNLESS OTHERWISE STATED



SEQUENCE OF OPERATION

1. Face one end roughly and turn to $\phi 81$ at a length of about 15 mm.
2. Clamp $\phi 81$ in the three jaw chuck and complete all turning, boring and threading operations as far as possible in this position.
3. Now use the workpiece to hold the screw from the previous exercise for the necessary operations.
4. Clamp $\phi 45$ and complete the base.

SCALE 1:1

MAT: MILDSTEEL

BASE FOR MOVEABLE SCREW

MP/2.3/4.1.1/12


TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SCALE 1:1

MAT: MILDSTEEL

BASE AND MOVEABLE SCREW

MP/23/4.11/12 a






TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SCALE 1:1
MAT: MILDSTEEL

SPINDLE AND CENTRE













MP/23/4.11/14
TURNING III



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

 <p>Exercising of known operations</p> <p>1 → 3</p>	 <p>Turning within small tolerances</p> <p>2 → 5</p>	 <p>Turnig of welded parts</p> <p>1 → 3 → 5</p>
 <p>Turning of internal grooves</p> <p>4 → 5</p>	 <p>Working on a four jaw chuck</p> <p>3.1.2/10 → 5 ← 2/3/4</p>	 <p>Work with steadyrest</p> <p>6</p>
 <p>Facing of grooves</p> <p>7</p>	 <p>Boring to high accuracy</p> <p>8 → 421/9</p>	 <p>Taper turnig</p> <p>9</p>
 <p>Exercising of known operations</p> <p>10</p>	 <p>Exercising of known operations</p> <p>11 → 4.2.1/11</p>	 <p>Eccentric shaft</p> <p>12</p>

In addition to the exercises shown above , the trainees have to make parts which are needed for the training centre.

TRADE
TRAINING III

LAYOUT

MP/2.1/4.1.2

TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

MATERIAL REQUIRED

TURNER

TRADE TRAINING III

TURNING IV

No. 4.1.2/1 to 12	Exercise No.												Length given in Millimeter)	Length per Trainee	Total length for 16 Trainees	Total weight for 16 Trainees					
	1,1	1,2	2	4	6	7	8	9,1	9,2	9a	10,1	10,2					11,1	11,2	12,1	12,2	12,3
M.S.Round ϕ 50 mm (2" DIA)	48				106						16	150	46						366 mm	5.9 meter	93.8 kg
M.S.Round ϕ 130 mm (5 1/4" DIA)	30																		30 mm	0.48meter	52.3 kg
M.S.Round ϕ 38 mm (1 1/2" DIA)		155					106	68											351 mm	5.62meter	47.6 kg
M.S.Round ϕ 75 mm (3" DIA)				16															16 mm	0.256 meter	9.0 kg
Cast Iron acc. to pattern																			casting		
Cast Iron ϕ 105 mm (4 1/4" DIA)					28														28 mm	0.45meter	30.5 kg "CASTING"
M.S.Round ϕ 102 mm (4 " DIA)						56													56 mm	0.9 meter	57.6 kg
M.S.Round ϕ 19 mm (3/4" DIA)											14								14 mm	0.224 meter	0.55 kg
M.S.Round ϕ 25 mm (1" DIA)												68		150	48	18			284 mm	4.6 meter	28.0 kg
M.S.Round ϕ 44 mm (1 3/4" DIA)													166	20					186 mm	3.0 meter	26.5 kg



Total Nos. per Trainee	Total Nos. for 16 Trainees
1 No.	18 Nos.

Cheese Head Screws
M 5 x 15 mm

DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

Tolerance ± 0.2



SCALE 1:1

MAT.: MILDSTEEL

FLANGE

MP/23/4.1.2/1


TURNING IV



DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING


PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Tolerance $\pm 0,1$
unless otherwise stated

64




25 _{f7}	- 20 - 41
32 _{g6}	- 9 - 25
8 _{N9}	0 - 36

SCALE 1:1	SHAFT	Mp/2.3/4.1.2/2
MAT.: MILD STEEL		TURNING IV

	DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING	TURNER
	PAK-GERMAN TECHNICAL TRAINING PROGRAMME	

Tolerance ± 0.1
unless otherwise stated.



SEQUENCE OF OPERATION

1. Hold workpiece on the rough machined $\phi 45$.
2. Machine the hole 25^{H7} , outside $\phi 120$ and step 72×4 .
3. Hold workpiece on a mandrel and finish the $\phi 44$.
4. Shape the keyway on a shaping machine.

SCALE 1:1

MAT: MILDSTEEL

From Ex.1

FLANGE

MP/21/4.1.2/3

TURNING IV




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

Tolerance $\pm 0,1$
unless otherwise stated




SEQUENCE OF OPERATION

1. Chuck workpiece in three-jaw chuck.
2. Face one side.
3. Re-chuck, use distance bush to ensure parallel faces and face to thickness.
4. Turn step, drill and bore to $\phi 26$.
5. Turn internal groove.
6. Hold workpiece on a mandrel and turn outside diameter.



TOOLS

- Bent roughing tool
- Right hand side tool
- Boring tool
- Form grooving tool

SCALE 1:1	BEARING COVER	MP/2.1/4.1.2/4
MAT: MILDSTEEL		TURNING IV
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER



Tolerance $\pm 0,1$
unless otherwise stated




Note: Assemble the bearing with shaft ex.2, flange ex.3 and bearing covers ex.4
Check for smooth running.

SCALE 1:1	CAST IRON BEARING	Mp 2.3/4.1.2/5
MAT. CAST IRON		TURNING IV
From 3.1.2/10		TURNER
DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		

▽ (▽▽)

Tolerance ± 0.1
unless otherwise stated

68



$25_{+0.016} = \begin{matrix} -0.020 \\ -0.033 \end{matrix}$

SEQUENCE OF OPERATION

1. Mark and punch centre.
2. Drill centre hole with the help of drilling machine.
3. Chuck and set the lathe centre.
4. Machine a groove for the jaws of the steady rest.
5. Set the steady and remove the lathe centre.
6. Machine to the required dimensions.
7. Part off to a length of 100 mm.

SCALE 1:1

MAT. MILD STEEL

SHAFT

MP/2.3/4.2/6

TURNING IV




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



Tolerance $\pm 0,1$
unless otherwise stated.



$$22^{H7} = \begin{matrix} +0,021 \\ 0 \end{matrix}$$

Check the hole 22^{H7} with a plug gauge.

SCALE 1:1

MAT CAST IRON

GEAR BLANK

MP/21/4.1.2/7



TURNING IV






DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING

PAK-GERMAN TECHNICAL TRAINING PROGRAMME

TURNER



SCALE 1:1	MILLING HEAD BODY	MP/21/4.1.2/8
MAT:MILDSTEEL		TURNING IV
	DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING	TURNER
	PAK-GERMAN TECHNICAL TRAINING PROGRAMME	



$\phi 18 k6$	$+0,015$ $+0,002$
$\phi 22 H7$	$+0,021$
$\phi 22 h6$	0 $-0,013$

SCALE 1:1	PARTS OF EXPANDING MANDREL	MP/2.1/4.1.2/9
MAT: MILDSTEEL		TURNING IV




DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING



1ST AK GERMAN TECHNICAL TRAINING PROGRAMME

TURNER

72.



Thread acc. to part No.1





1	Cheese head screw	5		M5 x 15
1	Cone washer	4		
1	Forcing nut	3		
1	Mandrel	2		
1	Taper shank	1		
Qty.	Denomination	Part-N.	Materil	Remarks


SCALE 1:1
MAT MILDSTEEL

EXPANDING MANDREL

MP/21/4.1.2/9a
TURNING IV



SCALE 1:1	CIRCULAR CUTTER	MP/2.3/4.12/11
MAT: MILDSTEEL		PART 1
 DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING PAK-GERMAN TECHNICAL TRAINING PROGRAMME		TURNER



SCALE 1:1	CRANKSHAFT WITH BUSH	MP/23/4 12/12
MAT. MILDSTEEL		TURNING IV
DEVELOPMENT CELL FOR SKILLED LABOUR TRAINING		TURNER
PAK-GERMAN TECHNICAL TRAINING PROGRAMME		

