

HANDWRITTEN
NOTES
OF

(MATERIAL SCIENCE)


BY

ENGGBUZZ.COM



material science:

- Relationship between structure and properties of Engg. materials




Ref.
 (1) material science & Engg. - Callister
 (2) material science - I.P. Singh.

Inside materials → molecular level bonding, ionic level bonding.
 Expressed as


- Properties:- Quantitative indices of behaviour (or response) of a material subjected to external stimuli.
 diff. types of stimulation, like optical, chemical, mechanical, magnetic, electrical - different type properties.

Structure : 3 levels.



→ Is defined as internal structure of a material which can be observed under the metallog → used for opaque samples
Optical microscope at high magnification of order of ($\geq 100X$).

→ microstructure consists of grains, grain boundary, phases, phase boundary & grain orientation (texture).




- Ferrite: - soft and weak
- Austenite: - Hard and ductile
- Tempered martensite: - Hard and Brittle

Macrostructure :-

Defined as External geometrical characteristics of a material which can be observed with naked eye or under the microscope at lower magnification of order of ($< 100\times$)

Microstructure :-



↳ properties dependents on defects in intermolecular bonding.

Crystal structure :-

⇒ To get stability, liquid metal crystallises into solid state by reduced minimising (potential energy of molecules)

atomic arrangement → Generally - Simple

- Body centered
- face centered
- End centered.


14 Bravais Lattice → low energy lattice, other 14 ^{maybe} are unstable at those condition.

- The crystal structures of unknown material can be determined by X-Ray diffraction technique.

⇒ macrostructure > microstructure > crystal structure.

Crystal system	Geometry	Bravais lattices
Cubic	$a=b=c$; $\alpha=\beta=\gamma=90^\circ$	<u>SC</u> , <u>BCC</u> , <u>FCC</u>
Tetragonal	$a=b \neq c$; $\alpha=\beta=\gamma=90^\circ$	<u>ST</u> , <u>BCT</u>
Orthorhombic	$a \neq b \neq c$; $\alpha=\beta=\gamma=90^\circ$	<u>SO</u> , <u>BCO</u> , <u>FCO</u> , <u>ECO</u>
Rhombohedral	$a=b=c$; $\alpha=\beta=\gamma \neq 90^\circ$	SR
Hexagonal	$a=b \neq c$; $\alpha=\beta=90^\circ$ $\gamma=120^\circ$	SH
Monoclinic	$a \neq b \neq c$; $\alpha=\gamma=90^\circ \neq \beta$	<u>SM</u> , <u>ECM</u>
Triclinic	$a \neq b \neq c$; $\alpha \neq \beta \neq \gamma \neq 90^\circ$	<u>ST</u> ,

Crystal systems (Basic shape of unit cells) & Bravais lattices (Atomic arrangement)



⇒ Crystal structure can be changed by Heat treatment and effect of alloying elements.

(FCC austenite \rightarrow BCC pearlite \rightarrow BCC martensite)

(1) Unit cell: - defined as smallest representative group of atoms which when repeated in all the crystallographic direction for a infinite no. of times results in the development of crystal lattice.

(2) Cry. lattice: A crystal lattice is defined as 3-D dimensional arrangement of lines in space. It is also called as a line lattice.

(3) space lattice: - 3D arrangement of points in space. it is also known as point lattice.

(4) Primitive cell: A simple cubic unit cell having atoms only at the corners \rightarrow

(5) lattice parameters: - Distance b/w centers of neighbouring corners atoms.

Crystal Structure characteristics:-

Crystal characteristics	Structure		
	BCC	FCC	HCP
atom relations	$a = \frac{4}{\sqrt{3}} r$	$a = \frac{4r}{\sqrt{2}}$	$a = 2r$
Av. no. of atoms (N _{av})	$= \frac{8}{8} + \frac{0}{2} + \frac{1}{1}$ $= \textcircled{2}$	$= \frac{8}{8} + \frac{6}{2} + \frac{0}{1}$ $= 1 + 3 = \textcircled{4}$	$= \frac{12}{6} + \frac{2}{2} + \frac{3}{1}$ $= \textcircled{6}$
Coordination Number	$= 8$	$= 12$	$= 12$
Atomic packing factor	0.68	0.74	0.74


***: Only crystalline materials are used 90-99%

\rightarrow Only metals are to be considered - thus BCC, FCC, HCP

\hookrightarrow Crystallisation into Body cent, Hexagonal

Let a = lattice parameter
 r = atomic radius.


BCC:-



→ one extra element atom at centre of body diagonals

→ AC = Body diagonal of unit cell

→ $AC = a\sqrt{3}$



$= a\sqrt{3} = 4r$


$$a = \frac{4r}{\sqrt{3}}$$

Example: Fe except (910-1400°C)
W, Cr, V, Mo, Ta, Na, Li etc.

BCC elements → generally hard & brittle.

addition of BCC element to increase the properties (hardness ↑, strength ↑, wear resistance ↑,

FCC:-





⇒ AB = face diagonal of unit cell

$$AB = a\sqrt{2}$$

$$AB = 4r$$

$$a\sqrt{2} = 4r$$

$$a = \frac{4r}{\sqrt{2}}$$





Example: - Fe in range of [910-1400°C]
Al, Cu, Ni, Pt, Au, Ag, Pb

→ str
FCC elements are "strong & ductile"

→ Toughness increase due to addition of "FCC". [area load-deformation increases].

⇒ Stacking sequence: → defined as the sequence of arrangement of atomic planes one above the other, in order to result in stability to the crystalline structure.



start
↓


↓^s

⇒ plane A-B-C-A-B-C-A-... ∞ constitute crystal

structure - stacking sequences will be ABCABCABC... ∞

HCP: -

$c =$ height of the unit cell



$$\Rightarrow \boxed{a = 2r}$$

\Rightarrow Stacking sequence \Rightarrow ABABABA $\dots \infty$

\Rightarrow for ideal HCP structure like Mg $\boxed{\frac{c}{a} = 1.633}$

Example: - Mg, Zn, Ti, Zr, Be, Cd, Co, Be,

\Rightarrow HCP elements are "generally less ductile compared to FCC elements".

\Rightarrow HCP \rightarrow less shear (due to weak bonding) \rightarrow easy shearing so used as solid lubricant (Graphite).

\Rightarrow Because of HCP "Be and Cd replaces the Pb in bearings" (babbit materials).

Avg no. of atoms

• defined as the no. of atoms which originally belongs to particular unit cell, calculated by following:

$$\boxed{N_{av} = \frac{N_c}{8} + \frac{N_f}{2} + \frac{N_i}{1}} \quad \text{[for cubic unit cells]}$$

$$N_{av} = \frac{N_c}{6} + \frac{N_f}{2} + \frac{N_i}{1}$$

(for HCP only)


N_c = no. of atoms at corners

N_f = no. of atoms at face centre.


N_i = no. of ~~atoms~~ interior atoms (inside the unit cell volume)

Co-ordination no

⇒ defined as the number of nearest and equidistant atoms surrounding an atom under consideration.



To find coordination no. of FCC



Atomic Packing factor:-

→ defined as "The ratio of volume occupied by the avg. no. of atoms to the volume of unit cell."

$$APF = \frac{\text{volume occupied by avg. no. of atoms}}{\text{volume of unit cell}}$$

$$APF = \frac{\frac{4}{3} \pi r^3 \times N_{av}}{\text{Vol. of unit cell}} = \frac{r^3}{\sqrt{3}} = \text{numerical value}$$

⇒ 6 equilateral triangles

for BCC

$$\text{Vol. of unit cell} = a^3$$


$$= \left(\frac{4r}{\sqrt{3}}\right)^3$$

FCC

$$\text{Volume of unit cell} = a^3$$

$$= \left(\frac{4r}{\sqrt{2}}\right)^3$$

HCP



$$\text{Volume of unit cell} = \text{base area} \times \text{height}$$

$$= () a^2 \times c$$

$$= () (2r)^2 \times (1.633)a$$

$$= () (2r)^3 \times (1.633)$$

Allotropy :-

• defined as tendency of an element to exist in different crystal structure at different temp and pressures.

→ allotropic transformation causes

(1) changes in density, volume

(2) change in coordination number → (index of stiffness) E will change

(3) more value of APF - less voids - more ductility.
more voidage - more brittleness

→ solubility ↑ with voidage.

Coordination no. indicates the (Bonding strength of atoms)

→ as material goes in state of high energy (Due to application of external load), the coordination helps to retain the original Bond length distance (after the


removal of external load)

Miller indices of planes:-

Rationalised Reciprocal of fractional intercepts, taken along the three ~~crystal~~ crystallographic direction and written inside parenthesis without a separating comma between them.

→ Indicated by (hkl)

→ ~~smallest~~ always expressed as smallest integers.



→ origin can be at any corner.

Ex 1 plane ABCD; X Y Z along X-axis $\Rightarrow OD = a = \frac{1}{1} a$

	X	Y	Z
(1) Intercepts	1	∞	∞
(2) Reciprocal	1	$1/\infty$	$1/\infty$
(3) Rationalisation	1	0	0
(4) Indices	(1 0 0)		

Ex 2 AFGD

	X	Y	Z
(1) intercepts \rightarrow	1	1	∞
(2) reciprocal \rightarrow	1	1	0
(3) Rationalisation \rightarrow	1	1	0
(4) Indices \rightarrow	(1 1 0)		

Ex: Plane DGE

	X	Y	Z
(1) Intercepts	1	1	1
(2) Reciprocal	1	1	1
(3) Rationalisation	1	1	1
(4) Indices	(1 1 1)		

Ex. A. plane BFGC


	X	Y	Z
→ Intercepts	∞	1	1
→ Reciprocal	0	1	1
→ Rationalisation	0	1	1
→ indices	(0 1 1)		

Exs plane EFGH

	X	Y	Z
intercept	0	0-1	0-1
Reciprocal	$\frac{1}{0}$	$\frac{1}{0-1}$	$\frac{1}{0-1}$
Rationalisation	∞	---	---
indices	(∞ , --- , ---)		

not defined

⇒ Shifting of origin 'o' at point 'D'



	X	Y	Z
intercept	-1	∞	∞
reciprocal	$\frac{1}{-1}$	$\frac{1}{\infty}$	$\frac{1}{\infty}$
Rationalisation	$\frac{1}{-1}$	0	0
indices	(1 0 0)		
	(1, 0 0)		

⇒ Characteristic of miller indices of plane :-

(1) When a plane is parallel to an axis, its miller index on that axis is zero

(2) Two parallel planes will have quantitatively the same miller indices

(3) Two planes (h_1, k_1, l_1) & (h_2, k_2, l_2) will be perpendicular if

$$h_1 h_2 + k_1 k_2 + l_1 l_2 = 0$$

(4) The angle ' θ ' between two intersecting plane (h, k, l) and (h_2, k_2, l_2)

$$\Rightarrow \cos \theta = \frac{h_1 h_2 + k_1 k_2 + l_1 l_2}{\sqrt{h_1^2 + k_1^2 + l_1^2} \cdot \sqrt{h_2^2 + k_2^2 + l_2^2}}$$

(5) Planes having low indices are far away from the origin than the planes having high indices.

→ Let d = interplane distance

$$d = \frac{a}{\sqrt{h^2 + k^2 + l^2}}$$

where (h, k, l) are miller indices of given plane


⇒ interplane distance denotes, distance between two parallel plane one of which is passing through the origin.

⇒ same as distance of given plane from origin.

$$\begin{cases} d_{(110)} = \frac{a}{\sqrt{2}} = \frac{a}{\sqrt{2}} \\ d_{(220)} = \frac{a}{\sqrt{8}} = \frac{a}{2\sqrt{2}} \\ d_{(330)} = \frac{a}{\sqrt{18}} = \frac{a}{3\sqrt{2}} \end{cases}$$

- Miller indices of directions: - Indicated as $[uvw]$
rationalised components of a given direction vector taken along the
3 ~~crystallographic~~ crystallographic directions.

→ always expressed as
smallest integers.



$$\vec{OA} = [OA]$$

$$\vec{OA} = [100]$$

$$\vec{OB} = \left[\frac{1}{2}, 0, 0 \right] \Rightarrow \vec{OB} = [100]$$

↓
not proper

$$\vec{OC} = [110]$$

$$\vec{OE} = \left[\frac{1}{2}, 1, 0 \right] = [120]$$

$$\vec{OF} = [111]$$

$$\vec{OG} = [100]$$

$$\vec{FG} = [100]$$

$$\vec{MN} = [100]$$

$$\vec{ON} = [001]$$

Characteristics of miller indices of directions:

(1) If a direction is perpendicular to an axis its miller indices on its that axis is zero

(2) Two parallel directions will have quantitatively same miller indices.

(3) Two directions $[u_1, v_1, w_1]$ & $[u_2, v_2, w_2]$ will be perpendicular if $u_1 u_2 + v_1 v_2 + w_1 w_2 = 0$

(4) The angle ' θ ' between two intersecting directions $[u_1, v_1, w_1]$ & $[u_2, v_2, w_2]$ is given by

$$\cos \theta = \frac{u_1 u_2 + v_1 v_2 + w_1 w_2}{\sqrt{u_1^2 + v_1^2 + w_1^2} \sqrt{u_2^2 + v_2^2 + w_2^2}}$$

(5) The plane & the direction having same miller indices will be perpendicular to each other.

Density Calculation in pure crystal structures:

There are three types of densities in crystal structures.

(1) Volume density: (ρ_v):

(2) Planar density: (ρ_{pl}):

(3) Linear density: (ρ_l):

Volume Density:

Volume density is defined as $\rho_v = \frac{\text{weight of } N_{av}}{\text{Volume of unit cell}}$

$$\rho_v = \frac{N_{av} \times \text{Atomic Wt.}}{\text{Volume of unit cell}} \left(\frac{\text{Gram atoms}}{\text{cm}^3} \right)$$

$$\rho_v = \frac{N_{av} \times \text{Atomic weight}}{[6.023 \times 10^{23}] \times \text{vol. of unit cell}}$$

(atoms)
(gr/mole)



(atoms/mole)
(cm³)

Planar density:-



⇒ Planar density is defined as the ratio of no. of atoms whose centers are intersected by a plane to the area of the plane itself.

$$\rho_{pla} = \frac{\text{no. of atoms}}{\text{Area of the plane}}$$

Plane	BCC	FCC
(1,0,0)	$\frac{1}{2}$	$\frac{2}{a^2}$
(1,1,0)	$\frac{2}{\sqrt{2}a^2}$	$\frac{2}{\sqrt{2}a^2}$
(1,1,1)	$\frac{1/2}{\sqrt{3}/2 a^2}$	$\frac{2}{\frac{\sqrt{3}a^2}{2}}$




no. of atoms intersected
By plane = $\frac{1}{4} \times 4 = 1$



= no. of atoms = $\frac{1}{4} \times 4 + 1$
= 2


plane (110)

BCC



no. of atoms
 $= \frac{1}{4} \times 4 + 1$
 $= 1 + 1 = 2$

plane (111):




area of triangle
 $= \frac{\sqrt{3}}{2} a^2$

~~no. of atoms~~


~~$= \frac{1}{6} \times 3$~~

BCC



$= \text{no. of atoms} = \frac{1}{6} \times 3 = \frac{1}{2}$

Note the centre of body centered atom will not be intersected by the ~~square~~ (111) plane in BCC structure, hence Body centered atom should not be counted in the calculation of planar density on (110) plane.




$d = \frac{a}{\sqrt{3}} = \frac{4r}{\sqrt{3} \cdot \sqrt{3}}$


$d = 1.333r$

$1.333 < 2r$

FCC




no. of atoms
 $= \frac{1}{4} \times 4 + \frac{1}{2} \times 2$
 $= 1 + 1$
 $= 2$



$= \frac{1}{6} \times 3 + \frac{1}{2} \times 3$
 $= \frac{1}{2} + \frac{3}{2} = 2$

dirⁿ (110)



BCC



no. of atoms
 $= \frac{1}{2} \times 2 = 1$

$$\rho_L = \frac{1}{\sqrt{2}a}$$



FCC



no. of atoms
 $= \frac{1}{2} \times 2 + 1$
 $= 2$



$$\rho_L = \frac{2}{\sqrt{2}a}$$

dir [1,1,1]



no. of atoms
 $= \frac{1}{2} \times 2 + 1$
 $= 2$

$$\rho_L = \frac{2}{\sqrt{3}a}$$



no. of atoms $\Rightarrow \frac{1}{2} \times 2 = 1$

$$\rho_L = \frac{1}{\sqrt{2}a}$$

\Rightarrow In crystal structures, the planes having highest value of plane density are called as closed packed planes or slip-planes.

For example in BCC structure ~~(111)~~ (110) is closed plane

whereas in FCC structures (111) is closed packed plane.

Similarly, The direction in crystal structures which have highest value of linear density are known as closed packed direction or slip directions.

For example! in BCC structure [1,1,1] is closed packed ~~plane~~ ^{direction}.

whereas in FCC structure [110] is closed pack ^{direction}.

→ no. of slip system defined as the product of no. of closed planes and no. of closed pack direction.

$$\boxed{\text{No. of slip System} = \text{No. of CPP} \times \text{No. of CPD}} \quad *$$

⇒ crystal structure → different planes have different plane densities then; a crystalline solids are Anisotropic.

⇒ [no. of atoms are different in different planes, no. of ~~pro~~ bonds different bands different properties will be]

⇒ no. of slip system → indicates (the plastic deformation) generally i.e ductility. (more no. of slip system, more will be ductility).

⇒ Slip → permanent deformation at low Temp & low stress
Twinning → _____ at low Temp & high stress

- Slip is due to motion of dislocation.

$$\boxed{W = F \times d}$$


as, $d =$ distance between atomic distance in CPP decreases.

less work to be done to move the dislocation.

⇒ By Resisting the movement of ~~slip~~ dislocation, ductility can be resisted and brittleness is promoted

→ thus, the above is done by cold working, work hardening

no. of slip system



⇒ Since BCC are having more no. of slip system, But they are brittle & because random orientation of closed packed planes resists the motion of dislocation, thus ~~increase~~ decrease the ductility. (Brittleness will be promoted). [The Reason of BCC to be Brittleness - Randomness]

⇒ FCC are having more no. of slip system than HCP, FCC are ductile & HCP are less ductile.

⇒ Due to randomness in orientation in neighbouring closed pack planes BCC is brittle.

Though FCC are having less no. of slip system than BCC, in FCC all closed pack planes are systematically aligned to facilitate to active movement of dislocation.

⇒ Ductile-to-brittle transition conditions:-

● under the following conditions even originally ductile materials will fail in brittle manner (1).

(1). low temperatures

(2). High strain rate

(3). Presence of surface notches

● In ~~add~~ addition to the above the following factors also contribute to the Brittleness in solids.

(1). Strain Hardening effect caused by cold working process.

(2). Residual stresses induced into the material by cold working or hardening treatment.

(3). Presence of internal carbide & nitride phases.

(4). low atomic packing factor (i.e. large voidage in the internal structures).

(5) Random Random Orientation b/w closed packed planes within internal structures.


- : Structural Imperfections :-

→ Deviation from True crystallinity. over a sharp range


Indices of True crystallinity :-

- * 3-D, long range, periodicity.
- * all atomic sites must be completely filled with own atoms.
- * Lattice should be at low potential energy.
- * Atoms must be at Bond length distance.
- * lattice must be stable.
- * Atomic planes must be discrete.


At absolute zero, all the conditions are satisfied but above absolute zero, then atoms are vibrating (at energy state).




already in other parts



point Defects:



⇒ due to unintentional heating, the atoms may escape and form a vacancies. (strength decrease at high temp).




⇒ self-interstitialcy / interstitialcy may increase the strength slightly. [The strength is temporary - because atom is not stable at interstitial space due to thermal excitation].

⇒ when a atoms goes into interstitial space (narrow spaces) → self-interstitialcy

⊕ when vacancies & self-interstitials space existing side by side → Frenkel defect.

⇒ Due to addition of foreign atoms ⇒ impurities in parent atoms.



→ substitutional impurities occupies the vacancies.
~~interstitial imp~~ interstitial impurities occupies the interstitial space.

→ ~~In ionic solids (when anion and cation) are~~

⇒ The Term **Vacancy** denotes the position vacanted by atom in parent metal lattice,

⇒ **Self-interstitialcy** denotes a parent metal atoms exists in a interstitial site.

⇒ **Impurities** denotes the A foreign atoms existing in a parent metal lattice.

Interstitial impurities: - A foreign atoms (smaller than parent metal atoms)

Substitutional impurities: - A foreign atoms (bigger than the parent metal atoms).

⇒ Frenkel defect: denotes a vacancy and self-interstitially existing together within a neighbourhood.

⇒ Schottky defect: denotes a pair of vacancy, due to cation and anion formed in ionic solids.

Let n_v = no. of vacancies in atom
 n_t = ~~no. of~~ Total no. of lattice site in a metal
 E = activation energy (enthalpy of formation of a vacancy)
 k = Boltzmann Constant
 T = Absolute Temp.

Then, n_v

$\frac{n_v}{n_t}$ = Vacancy concentration / fraction of vacancy sites in a metal

$$\left(\frac{n_v}{n_t} \right) = e^{-\left(\frac{E}{kT} \right)}$$


⇒ Above expression, vacancy concentration in a metal increases with increase in temperature.


Reason for point defect:-

- (1). Vacancies are formed due to thermal excitation caused by heating externally.
- (2). Impurities are formed, when alloying atoms are added to pure metal.

Effects of point defects:-

- (1) Vacancy formation results in decrease in strength of metal.
- (2) Impurity formation results in lattice distortion.





- ⇒ Due to this, randomisation of closed pack planes will take place,
- moving dislocation will be stopped,
- slip gets arrested,
- Resistance to permanent deformation increases.
- Hence, strength & hardness of metal increases, ductility decreases & Brittleness increases.

→ Due to which (impurities) → alloys are more stronger than pure metals.

d_{IM} = dia. of interstitial impurities

d_{PM} = dia. of parent metal atom

d_{IV} = dia. of interstitial void:

$$d_{IM} < d_{PM}$$


$$d_{IV} < P_{PM}$$

→ $d_{imp} > d_{IV}$ ~~large~~ practically;


↳ such distortion is possible with interstitial impurities.

Line Defects: (Dislocation):

A dislocation is defined as the boundary b/w slipped and unslipped portion of crystal.



+ve Edge dislocation




-ve edge dislocation

unslipped part
slipped part


shear component will only be responsible for dislocation movement
neighbouring
Exchange of vacancy (called slip)
such a mass transpos

1 2 3 4



→ separated plane
lost their separation,
then became helix.

⇒ screw dislocation → mass transport via helical path.



[lower boundary of partial plane]
Vacancies below dislocation line
[+ve dislocation line]

= dislocation (group of atoms) is moving → (1 → 2 → 3 → 4) →

⇒ Burger's vector (\vec{b}) :- which is used for characterization of movement of dislocation within a lattice

⇒ ~~is~~ Burger's vector of edge dislocation is perpendicular to dislocation line

→ Edge dislocation have two degrees of freedom, they are.

* glide motion :

* climb motion :

⇒ Glide motion, denotes the movement of edge dislocation parallel to closed packed plane. (permanent deformation at low Temp.)
whereas

climb motion, denotes the movement of edge dislocation perpendicular to the closed packed plane. (permanent deformation at high Temp.)

→ Glide motion → contribute slip

→ Climb motion → contribute cross slip

→ When a truly crystalline material is subjected to shear force, a discreteness of the atomic planes may be lost and gets converted into surface of a helix around a dislocation line. This type of structural deviation from true crystallinity is known as screw dislocation.

⇒ Burger's vector of screw dislocation is parallel to dislocation line

⇒ Screw dislocation contribute to permanent deformation at high temp.

⇒ no. of dislocation → depends upon manufacturing process.

⇒ Highest no. of dislocation → cold working process

Interactions between dislocation:

⇒ When two opposite edge dislocation travels towards each other on the same slip plane, they attract each other and combine into a perfect plane.

⇒ When two opposite edge dislocation travels towards each other on parallel slip planes a group of vacancies formed between them

⇒ When two similar edge dislocation travels towards each other on the same slip planes, they repel each other.

When a truly crystalline material is subjected to shear force, a discreteness of the atomic planes may be lost and gets converted into surface of a helix around a dislocation line. This type of structural deviation from true crystallinity is well known as screw dislocation.

Burger's vector of screw dislocation is parallel to dislocation line

Screw dislocation contribute to permanent deformation at high temp.

⇒ no. of dislocation → depends upon manufacturing process.

⇒ Highest no. of dislocation → cold working process *

Interactions between dislocation:

⇒ When two opposite edge dislocation travels towards each other on the same slip plane, they attract each other and combine into a perfect plane.


⇒ When two opposite edge dislocation travels towards each other on parallel slip planes, a group of vacancies formed between them.

⇒ When two two similar edge dislocation travels towards each other on the same slip planes, they repel each other.

Surface Defects: (2-D defects)

(1) Grain Boundaries:-

→ formed during solidification of metals:



⇒ A dendrite is defined as randomly growing solid phase in the molten metal.

⇒ Grain boundary is defined as the junction b/w two randomly growing dendrite.

dendrite] Grain is same as dendrite


⇒ Characteristics of grain boundaries:

(1) Regions of High Energy. (interatomic distance reduces due to Randomly going ~~point~~ dendrites)

(2) GB → Regions of Orientation of mismatch

(3) GB → low melting point Regions.

(4) GB → Regions of heavy impurity concentrations. (slag inclusions, gas pores)




⇒ fine grains structure more strength than coarse grain at low temp. only

at low Temp
⇒ dislocation are resisted by grain boundaries
↓
more grain boundaries → more fine grains → more hardness & strength:-

at high temp → Grain boundaries gets melted (to minimize grain boundaries at high temp)...


→ Grain boundaries corroded fast- (hence for corrosion resistance less no. of grain boundaries).

→ Single crystal materials are materials having zero grain boundaries in them. they are developed by special manufacturing process called as crystal pulling method.



at low temp

G - Relatively weaker
GB - stronger



at High temp


G - stronger
GB - weaker

For better creep resistance, coarse grain structures are preferred.

Equi-cohesive temp.


→ defined as the temp. at which both grains and grain boundaries will have same strength.

2) low angle boundaries :-



Dislocation pile-up (dislocation are accumulated at the grain boundaries)

⇒ When two or more no. of edge dislocations are accumulated one above other in a grain boundary, the resulting lattice will be called as low angle tilt boundaries.




→ lattice distortion occur due to dislocation
Thus there no. of dislocation accumulated at the grain boundaries, there will be more lattice vibration.

→ So lattice vibration caused by

When similar lattice distortion takes place due to accumulation of skew dislocations one above the other in a grain boundary, it is known as low angle twist boundaries.

(III) Twin Boundaries:



⇒ When a purely crystalline material subjected to shear distortion, the atomic arrangement in slipped and unslipped portion of the crystal will become mirror images of each other, about two boundaries. These two boundaries are known as twin boundaries.

⇒ Twin boundary formation results in increased net potential energy of lattice and makes it unstable and non-uniform property will be present in the lattice.

(IV) Stacking faults: all faults in stacking sequences.


⇒ Stacking sequences in FCC: $ABCABCABC \dots \infty$

in HCP: $ABABABAB \dots \infty$

- (escape of group of atoms plane)

- stacking fault formation results in increase in net potential energy, makes it unstable and non-uniform properties will be present in the lattice.

Strengthening mechanisms



Hot working → improve the grains size and causes the ~~etc~~ formation of grain boundaries → Grains are refined.

Heat treatment: Grains size are refined.

Hall-petch eqn

$$\sigma_y = \sigma_i + k \cdot d^{-1/2}$$

σ_y = yield stress of polycrystalline material

σ_i = yield stress of the material at an infinite grain size.

k = Hall-petch constant

d = Avg. grain diameter.

Cold working cold working of metal results in increasing ~~the result~~ the no. of dislocations due to this entropy of lattice increases.

→ (due to this randomness between closed pack plane will increase the dislocation movement will be stopped, slip gets arrested and resistance to permanent deformation increases. Hence Ductility decreases)

→ Brittleness increases, because, strength & hardness increases by cold working. (Strain hardening process).

→ This increase in hardness & strength by cold working is known as strain hardening or work hardening.

Solid Solution Strengthening

• Solute - (impurities like)

• Solvent - parent

→ Reason for strength improvement by solid solution strengthening is lattice distortion caused by solute impurities.

→ More significant improvement in strength solid strengthening the following two suggestions are made.

(1) Increase the concentration of (impurities) solute

(2) Increase the size difference b/w (solute (impurity) ~~and~~ and solvent (parent metal).

* concentration of solute, ↑ (Prevalence of Precipitation)

* Atomic size ~~of~~ difference of between solute & solvent.

Huth-Rothery's Rule for extensive solid solubility: →

(1) Crystal structure factor:

The crystal structure of both the elements should be the same.

(2) Relative size factor: - (< 15%)

The difference in atomic radii b/w the two elements ^{should be} ~~total~~ less than [^] 15%.

(3) chemical Affinity factor: -

Greater the chemical affinity b/w the two elements, more restricted will be the solubility.

(4) Relative Valency factor: -

An element of lower valency can dissolve more amount of another element of higher valency. than the reverse.

Alloy

→ An alloy is defined as any substance having metallic characters and composed of two or more no. of chemical element out of which atleast one is a metal

phase: defined as microstructurally ~~distinct~~ distinct and chemically homogenous & mechanically separable part of system.

find
To no. of phases (P), Gibb's equ.

$$P + F = C + 1$$

stands for Temp as the only variable in the study of alloy phases.

→ f = degree of freedom

→ P = no. of phases.


→ C = ~~no. of components~~ no. of chemical elements, used in alloy formation &

- if degree of freedom = 0; in any alloy transformation, such a process or reaction is known as invariant reaction.
- if F = 1; the resulting transformation in alloy is known as uni-variant reaction:
- if F = 2; The resulting transformation in alloy is known as bi-variant reaction:

classification of Binary alloy:-

① Homogenous alloys / single phase alloys

② Mixtures (Multi-phase alloy)



Solid solutions


1. made on percentage weight % basis

2. concentration of solute is variable

3. produced due to mutual dissolution of two metals.

4. Cannot be expressed as a chemical formula. They are indicated by greek letters. In microstructure and phase diagrams.

5. Solid solution melts or solidify over a range of temp. known as melting range or freezing range.



(6). Are addressed by ~~major~~ ~~minor~~ ~~common~~ ~~minor~~

"minor element in major element"

Ex: α -ferrite

Solid solution of C in Fe

Duralumin

Solid solution of Cu in Al

Compounds


1. made on molar volume basis.

2. molar volume ratio remains constant

3. produced due to chemical reaction.

4. Compounds can be expressed as chemical formula:

5. Compound melts or solidify at constant temp. like pure metals.



(7) "major element & minor element"

Ex: Fe_3C

→ compound of iron and carbon

$MgPb$
 O_2

→ compound of Mg & Pb

Mg_2Sn

→ compound of Mg and Sn.

→ less chemical affinity, more solid solubility.

→ on the basis of valency, the solute and solvent are characterized.

→ lower valency → Solvent:

→ Higher valency → Solute:

Relative valency factor **

→ Composites:

Always 2 phase materials

① matrix

② Reinforcement (Discontinuous)


→ In the manufacturing of Composites the Reinforcement material is so selected that it has superior properties than the matrix material.

→ Composites are classified as.

①

Particulate Composites

↓
Hard particles of carbides are dispersed into soft molten ~~matrix~~ metal:



'or' (SiC).

↓
Dispersion strengthening Carbide are hard ~~and~~ having less high melting point, they do not melt and no molecular Atomic Bonding → Thus they resist the motion of dislocation.

②

Fiber Reinforced ~~composites~~ composites

→ The fiber denoted line thread like structure from metallic or non-metallic family.

→ In the manufacturing of fiber reinforced composites, fiber material is so selected that its young's modulus (E) more than that of matrix material.

$$E_f \gg E_m$$

→ The properties of fiber Reinforced ~~composites~~ composites depends upon:

① Size/shape/distribution of fibres in the matrix.

② Aspect ratio of fibre
 $\left(\frac{l}{d}\right)$

③. fiber matrix interfacial bond strength.

④. relative orientation of axis of the fibre w.r.t. to σ direction of external

③

Laminated Composites (claddings)

load applied.

- The major objective fibrelly Reinforcement composite is to improve the stiffness of composite. The stiffness of composite material can be calculated using the rule of mixture given below for various loading condition:

let E_f = Young's modulus of fibre

E_m = Young's modulus of matrix


$$E_f \gg E_m$$

V_f = volume ^{fraction} of fibres

V_m = Volu. fraction of matrix.


⇒ Estimation of young's modulus of composite (E_c) :-
(Rule of mixtures):

(1) longitudinal loading: (Isolation condition):



$$E_c = E_m V_m + E_f V_f$$

(2) Transverse loading (Iso stress condition):



$$E_c = \frac{E_m E_f}{E_m V_f + E_f V_m}$$

$$\frac{1}{E_c} = \frac{V_f}{E_f} + \frac{V_m}{E_m}$$

⇒ For a given volume fraction of fibres, a fibre reinforced composite will exhibit superior stiffness in longitudinal loading rather than in transverse loading [Ex]


→ CFRP: ~~very costly~~ Carbon-fibre Reinforced Polystyrene

→ GFRP: Glass-fibre Reinforced Polystyrene.

→ CFRP exhibits superior stiffness compared to GFRP composites.

3 laminated composites: (claddings):

Ex: Bimetallic strips



⇒ The objectives of laminated objectives are: ① to improve surface properties like electrical, magnetic properties ② to improve corrosion resistance like ~~wear~~ wear resistance, fatigue resistance, creep resistance.

③ To improve uniformity of heat distribution in various applications.

Some practical:

* Al-clad: → Aluminium cladding → denotes high purity aluminium layer bonded to commercial purity aluminium, for use in aerospace industry, for light weight & good corrosion resistance.

* Cu-clad-Al: → used for improving creep resistance of aluminium.

* Cu-clad steel: → denotes copper layer bonded to steel stainless steel for uniformity of heat distribution in cooking.

Phase diagrams:

[Constitutional diagram & equilibrium diagram]


Type-I phase diagrams :- Isomorphous System:

→ In this system of alloy the two elements added will exhibit the complete solubility in both liquid & solid state.

Examples are: copper-nickel [Cu-Ni], ~~Au-Cu~~ [Au-Cu],
Gold-silver [Au-Ag],
moly-Tung. [Mo-W].


⇒ isomorphous - same crystal structure [Both must have same crystal structure]

⇒ phase diagrams for single phase alloy.



→ the solidification and liquid point temp. are measured according to the composition.

then plotted against temp-composition curve - called phase diagram.



Uses:-

(I) Tie line Rule Tie line is a horizontal line drawn at any given temp.

let $T^* =$ any given temp

\Rightarrow It is used for determination of composition of liquid and solid phases existing in an alloy at any given temp.

(II) Lever Rule:- let $z^* =$ Any given composition


\Rightarrow Lever Rule is used for determination of relative amount of liquid and solid phases existing in an alloy of given composition.

\Rightarrow At a specific temp.

let $z^* =$ any given composition.

point of intersection of z^* and Tie line ($F \rightarrow$ fulcrum).

lets:-



According to lever Rule,


$$\text{amount of liquid } (L) = \left(\frac{FD}{CD}\right) \times 100$$

$$\text{amount of solid } (S) = \left(\frac{CF}{CD}\right) \times 100$$


$$L + S = \left(\frac{CD}{CD}\right) \times 100$$

$$L + S = 100\%$$


(III) cooling behaviour :- [of Isomorphous alloy]




→ in every region '2' point, every neighbouring region have common point



between 1 and 2



between 2 and 3



between 3 and 4

Type-II Eutectic system →


⇒ In this system of alloys, Two elements added will exhibit complete solubility in the liquid state & complete insolubility in solid state

Complete Example Pb-Ag, Bi-Cd, Au-Si

Let M = melting point of element 'A'
 N = melting point of element 'B'

⇒ Raoult's law states that...


⇒ When ~~an~~ impurity is added to pure metal, its ~~metal~~ melting point Temp. decreases.




⇒ $MPEQN$ = solidus-curve

⇒ Cooling behaviour of eutectic alloys :-


two zones 1-2, 2-3



between 1, 2




between 2 and 3




⇒ interlamellar structure of A & B

Cooling


Cooling behaviour of Hypoeutectic alloys:



b/w 1 and 2




b/w 2 and 3




b/w 3 and 4


Cooling behaviour of hypereutectic alloys:




b/w 1 and 2



dendrite of 'B'



Interlamellar structure of A and B



⇒ composition of liquid
 ⇒ going towards
 Eutectic composition
 thus at last
 the & liquid will
 be solidified at
 point E and
 interlamellar
 structure will be
 formed.


Type-III partial Eutectic system:-

⇒ In this system of alloys the two elements added will exhibit complete solubility in liquid state and partial solubility in solid state.

Ex: Ag-Cu alloys, Pb-Sn, Sn-Bi, Pb-Sb


Let m = melting point of 'A'
 n = melting point of 'B'
 E = Eutectic
 MEN = Liquids
 $MPEQN$ = Solids.

→ Roult's law is valid for partial eutectic alloys.




Solid
 Let α = solution of B in A.
 β , B = solid solution of A in B.

cooling behaviour of eutectic alloys:-




interlamellar structure of α' and β'

cooling behaviour of hypoeutectic alloys




interlamellar structure of α and β

Cooling behaviour of hyper eutectic alloys:-




as temp. ↓, solubility ↓, thus 'β' or 'α' will precipitate out of ~~the~~



Type-IV layer system phase diagrams:

→ In this system the elements added will exhibit complete insolubility in both liquid and solid.

Ex: ~~Cu~~-W, Cu-Mo, Ag-Au, Ag-W etc.



let M = melting point of 'A'

N = melting point of 'B'


→ These alloys are not formed ~~but~~ in casting, But can be produced using powder metallurgy.

⇒ for insolubility -
(1) melting temp. difference will be there
(2) High density difference.


Iron & carbon diagram


Iron - Iron carbide diagram :-

Cooling curve of pure iron :-



⇒ ferromagnetic into paramagnetic iron [when $T_{emp} > 768^{\circ}C$]





- ⇒ Slow quenching — Equilibrium diagram
- ⇒ Fe_3C → very hard & brittle [no practical application].
- ⇒ difficult to add 'C' to Fe, because of sublimation tendency of 'C'.

Definition of important phases:-

- * α - ferrite
- * γ - Austenite
- * δ - ferrite
- * Fe_3C - cementite (compounds)

① α -ferrite:

→ Interstitial solid of 'C' in α -iron ~~with~~ which is pure ^{form} of iron, with BCC and $N_{av} = 2$, and non-magnetic properties.

② γ -austenite:

→ Interstitial solid solution of 'C' in pure γ -iron with FCC structure and $N_{av} = 4$, and non-magnetic properties.

③ δ -ferrite:


→ interstitial solid solution of 'C' in pure δ -iron with BCC structure and $N_{av} = 2$ and non-magnetic properties.

④ Fe_3C :

→ interstitial compound of 'C' in ~~pure~~ of iron and carbon having solubility of 6.67% of 'C'.

Invariant Reaction:

(I) peritectic Reaction \Rightarrow (at $1492^\circ C$, 0.18% C)




let $\delta \rightarrow S_1$

let $\gamma \rightarrow S_2$

let $Fe_3C \rightarrow S_3$

(II) Eutectic Reaction \Rightarrow (at $1147^\circ C$, 4.3% C)




($\gamma + Fe_3C$) mixture \rightarrow ledeburite






let $\alpha \rightarrow S_4$

(III) Eutectoid Reaction: (at $723^\circ C$, 0.8% C)



($\alpha + Fe_3C$) mixture \rightarrow pearlite






→ only one decomposition reaction → Eutectoid Reaction
austenite \rightleftharpoons $\alpha + \text{Fe}_3\text{C}$

Solubility of Carbon in various phases:-

- (1) Carbon solubility in δ -ferrite is 0.1%.
- (2) Carbon solubility in γ -austenite is 2%.
- (3) Carbon solubility in α -ferrite is ~~0.0025~~ 0.025% (at 723°C)
- (4) Carbon solubility in α -ferrite at room temp. 0.008%.
- (5) Carbon solubility in cementite is 6.67%.

Some critical temp. line and their significance:

- (1) A₁ → line → lower critical temp. line.
→ This line signifies the transformation of pearlite into austenite upon heating of eutectoid steels.
- (2) A₂ line → Curie point temp. line.
→ It signifies, the magnetic to non-magnetic transformation which takes place in Iron-carbon system of alloy during heating.
- (3) A₃ line: upper critical temp. line for hypo-eutectoid steels.
→ This line signifies the transformation ferrite into austenite upon heating of hypo-eutectoid steels.
- (4) A_{cm} line: upper critical temp. line for hyper-eutectoid steels.
→ This line signifies the transformation of cementite into austenite upon heating of hyper-eutectoid steels.



Heat treatment

→ Recrystallisation temp of steel (625-725°C)

(1) Annealing → medium-C steels

(2) Normalising → High carbon steels

(3) Hardening → High carbon steels

(4) Surface Hardening (Case Hardening)

→ Carburising → low C steels

→ Nitriding → low C steels

→ Cyaniding → low C steels

→ ~~Case~~ Induction Hardening → high-C steels

→ Flame Hardening → high-C steels

Annealing

* steel is heated to completely (γ -austenite range) (+500-1000) about it

* Held at that point for 30-60 min. for uniform austenization.

* followed by cooling to room in the furnace itself.

Consequences:

Recovery


• Residual stresses are completely removed.

• Ductility recovered.

• formality ↑

Recrystallisation

formation of new (stress free) equi-axed fine grain structures from coarse columnar grain structure of previously cold worked metal.



Recrystallisation (solid transformation process)

Grain growth.

⇒ Strength will ↓ decrease
⇒ Hardness will ↓ decrease
⇒ coarse grains are formed
⇒ machinability ↑

→ By annealing → Austenite converted into coarse pearlite.

Normalising:-

- steel is completely (γ -range) [or $+(50-100)$ above it].
- held at that temperature for $\sim 30-60$ min, for uniform austenitisation to take place.
- followed by cooling to room temp in open air.

Consequences:-

- * fine grain structure
- * more strength & hardness
- * less machinability
- * ductility less
- * formability will be less
- * Residual stresses partially relieved

→ due to faster cooling rate, there is not enough time for grains to grow

compared to annealed steel.

⇒ Austenite transforms into fine pearlite:


Hardening process:

- In hardening, high carbon steel is heated to completely ^{to} about 1000°C followed by sudden cooling (quenching) in water.
- quenching media → molten Pb, molten NaCl, heated oil, Brine solⁿ.

Consequences:-

- * Residual stresses are induced [due to sudden quenching]
- * surface cracking [quench cracking]
- * corrosion can take place (metal oxide)
- * distortion of shape can take place.
- * Retained austenite formation take place.

⇒ not enough time for carbon, thus martensite goes to BCT
(Body centred Tetragonal) due to having more carbon than its capacity at room temp.



- ⇒ Complete austenite are not transformed to martensite; thus some austenite is retained.
- ⇒ Retained austenite is unstable → (with decreasing temp. austenite goes FCC to BCC) Because (at low temp. FCC is not stable in iron).
- ⇒ Retained austenite is unstable at room temp. It brings about dimensional changes in the previously hardened component. Hence it should be eliminated.
- ⇒ Characteristics of austenite to martensite transformation

- * $\gamma \rightarrow$ martensite at the speed of sound in the material being quenched.
- * $\gamma \rightarrow$ martensite transformation, does not depend on the time.
- * $\gamma \rightarrow$ martensite transformation, is diffusionless process.
- * $\gamma \rightarrow$ martensite transformation, takes place by the process of "shear." [cooling stress causes shear, shear component of compress. cooling stress]
- * $\gamma \rightarrow$ martensite transformation, never goes to hundred 100% completion at room temp. (Retained austenite formation takes place).

Note:

$\gamma \rightarrow$ austenite ~~transformation~~ transformation, time-dependent, and diffusion process.

mass transport can take place → ① time depend diffusion
② time independent shear mechanism.

Method of elimination of austenite

- * ~~sub-zero cooling~~ sub-zero cooling.
- * Permanent deformation:
- * High temp. tempering:

(1) sub-zero cooling:


- at $[-37^{\circ}\text{C}]$ 100% completion of $\gamma \rightarrow$ martensite.
- use cryogenic liquids [liquid N_2 , liquid N_2]
- Retained Austenite goes into martensite

(2) permanent deformation:-

- By adding uniform deformation [using hydraulic press], By shearing \rightarrow ~~BE~~ $\gamma \rightarrow$ BCT (martensite)
- only anisotropic transformation which is influenced by pressure. But pressure changes only a small amount of crystal structure

(3) High temperature tempering:- [$550^{\circ} - 650^{\circ}\text{C}$]

- Reheating to high temp, holding for long time and then gradual cooling



- previously hardened component
- no significant changes in martensite ($R_c = 65$)

- Residual stresses are relieved
- Ductility increases (Toughness increases)

and $\gamma_{RA} \rightarrow$ Bainite
 $R_c = 55$
↓
Rockwell Hardness number on 'C' scale.

⇒ High temp. tempering of alloy steel, due to precipitation of alloy elements ~~precipitation~~ carbides, → which cause hard & brittleness!

Martempering → quenching in different stages.

Austempering: → quenching in molten Pb, [Pb is kept at high temp for long time]

→ from 100°C to molten Pb temp.

Ausforming → Rapid cooling to A_1 line and then metal forming process.

Surface Hardening :-

① Carburising → low C steels → high C steels

- In the presence of charcoal → solid (pack) carburising.
- when heating in molten NaCN → liquid (~~pack~~) carburising.
- using flue gas, carbon atoms into steel → gas carburising.
- need for quenching.
- High carbon steels → surface austenite → martensite. → 800 VHN

② Nitriding: faster than carburising

- ↳ Nitrides more hard than carbon → 1100 VHN
- ↳ But brittle surface formation → less life of component

③ Cyaniding (Carbon nitriding) :-

- ~~NaCN~~ molten salt NaCN →
- ⇒ where carbon → necessary to quench to improve hardness is true on surface ↗
- 1000 VHN →
- cyaniding cases are having more life.

④ Induction :- due to induction, secondary current are generated on surface.

- minimum requirement of supply 2 KHz, so need high frequency (costly).

⑤ Flame :- using neutral flame → used for cast iron

- cheapest for large surfaces.

Cast irons:

1. good damping capacity

2. Good wear resistance

3. self-lubricant (due to graphite flakes)

4. high compressive strength


5. (3-4 times of tensile strength) = compressive strength

6. ~~at~~ (form stability) → to retain its shape.

→ flame hardening and tempering is used to relieve stresses.

→ pipe

Pig iron - raw material



Effect of alloying elements:

Elements	Effects
<u>(1)</u> Silicon: potential deoxidizers → It is a solid solution strengthener i.e. it dissolves in ferrite & increases tensile strength & toughness without decreasing ductility.	potent → silicon increases Resilience in Spring steels → silicon makes the steels magnetically soft. for use in electrical application.
<u>(2)</u> Sulphur :-	It reacts with iron and produces iron-sulphide inclusions → sulphur induces cracking tendency at high temperatures. → Sulphur iron-sulphide inclusion has low melting point temp, aggregate along the grain boundaries and increases brittleness of steel.
<u>(3)</u> Phosphorus:-	→ It reacts with iron and forms iron-phosphide which makes the steel brittle. → phosphorus increases machinability

If added in small quantity

→ phosphorus induces cracking tendency at low temp. known as - cold shatterness.

(4) Manganese (Mn)

- manganese dissolves in ferrite increases tensile strength and hardness, wear resistance.
- manganese promotes cracking tendency during quenching.
- manganese is an austenite stabilizers, when added in small quantities, ~~mn~~ Mn improves machinability of steel.

(5) Ni (nickel)

- austenite stabilizers.
- nickel increases corrosion resistance & toughness without decreasing ductility.
- nickel decreases the coefficient of thermal expansion in steels.

(6) Cr, W, V, Mo & Ta,

- all carbide-forming elements.
- they increase hardness and wear resistance.
- They are used as grain size refiners.

Note → Cr → predominates increases corrosion resistance

→ W → predominately increases hot strength

→ Mo → predominately increases creep resistance

→ V → predominately increase fatigue resistance

→ Ta → predominantly increases hot hardness and creep resistance.

(7) Boron (B)

→ it refines grain size, increases surface hardness.

→ Corrosion resistance, wear resistance. ~~ductility~~

(8) Tantalum (Ti)

→ strong carbide forming elements

→ it increases the creep resistance & refines the grain size.

(9) Niobium (Nb)

→ It forms stable carbides, increases hot hardness and creep resistance

• Characteristics of ceramics :-


- SiC → metalloid/carbide (not a ceramic).
- Hard and brittle
- Insulators of Heat
- at high temp → they shaw

⇒ Stable crystal structures are formed in ceramics according to the following principles :-

(1) minimum radius ratio b/w cations and anions.

(2) Electrical charge neutrality in the lattice.


(3)



→ stable (minimum radius must be to stable) depends on the coordinates

→ simplest coordination

- In trigonal coordination, the coordination no. of cations is 3.
- In tetrahedral co-ordination, the coordination no. of cations is 4.
- In Octahedral co-ordination, the co-ordination no. of cations is 6.



- In cubic coordination, coordination no. of cations is 8
- In FCC, HCP coordination, coordination no. of cations is ~~12~~ 12.

$r_a = \text{radius of anion} = CK = CM$

$r_c = \text{radius of cation} = KD$

$\Rightarrow CD =$

from $\triangle CMD$

$$\cos \alpha = \frac{CM}{CD} = \frac{r_a}{r_a + r_c}$$

But

$\alpha = 30^\circ$, therefore

$$\cos 30 = \frac{\sqrt{3}}{2} = \frac{r_a}{r_a + r_c}$$



$$\Rightarrow \frac{r_a \left(\frac{\sqrt{3}}{2} \right)}{2} = 2r_a =$$

$$\left(\frac{\sqrt{3}}{2} \right) r_c = r_a - \left(\frac{\sqrt{3}}{2} \right) r_a$$

$$\Rightarrow \frac{r_c}{r_a} = \frac{2 - \sqrt{3}}{\sqrt{3}} =$$


$$= \boxed{\frac{r_c}{r_a} = 0.1547 \approx 0.155}$$

$\Rightarrow r_c < r_a (0.155) \rightarrow \text{unstable}$



\Rightarrow The above expression gives minimum radius of cations, required to make a stable crystal structure in trigonal co-ordination.

Zinc Blende (ZnS) structure :-



- \rightarrow coordination no. of anion $(Zn^{+2}) = \underline{4}$
- \rightarrow Tetrahedral coordination \leftarrow

Nav of $\bar{S}^2 = 4$

→ each \bar{S}^2 gives a charge = -2

∴ electrical charge due to \bar{S}^2 ions = -8 [4×-2]

→ each Zn^{+2} gives a charge = $+2$

no. of Zn^{+2} ions needed for charge neutrality = 4

• All plastics are polymers ?? or polymers are plastics ??

→ Natural polymer - all not poly plastic

→ when synthetic polymer are called as plastics when additives are added to it.

additives are - for plastics:-

(1). fillers → strength ↑ & hardness ↑

(2). stabilizers → provide protection against UV radiation

(3). plasticizers → ductility.

(4). dyes & pigments → colouring agents.

(5). fire retardants → protection against fire and flames



cross linked → Rigid structure formation



→ Thermosetting exhibit ~~the~~ sublimation tendency

→ thermosetting → decomposition → ~~plastic~~



Q Find the dia. of largest imaginary sphere which can be filled in voids at the centre of cube edge of BCC crystal.

Soln




$$d = a - 2r$$

$$a = \frac{4r}{\sqrt{3}} \Rightarrow r = \frac{\sqrt{3}a}{4}$$

$$d = a - \left(\frac{\sqrt{3}a}{4}\right) \cdot 2$$

$$\boxed{d = 0.1339a}$$

Q Find the dia. of largest imaginary sphere which can be filled at the centre edge of an fcc crystal.



$$\Rightarrow d = a - 2r$$

$$d = a - \frac{2\sqrt{2}a}{4}$$

$$\boxed{d = 0.2929a}$$

Note above two problems, it can be noted that interstitial void size in fcc is more than interstitial void size in BCC

Quest . Cu have fcc structure, its atomic radius is 1.28 \AA and atomic mass is 63.5 calculate its density.

Soln

$$\rho_v = \frac{4 \times 63.5}{6.023 \times 10^{23} \times \left(\frac{4}{\sqrt{2}} \times 1.28 \times 10^{-8} \text{ cm}\right)^3}$$

$$\rho_v = 8.897 \text{ gm/cm}^3$$

Quest A plane intersects the ~~coordinate~~ axes at $(x = \frac{2}{3})$ $y = \frac{1}{3}$
 $z = \frac{1}{2}$
 what are miller indices.

what are miller indices.


Sol

	X	Y	Z
<u>int</u>	$\frac{2}{3}$	$\frac{1}{3}$	$\frac{1}{2}$
<u>Recip</u>	$\frac{3}{2}$	3	2
Ratio	6 3	6	4

miller [3 6 4]

Quest At room temp α -iron contains negligible amount of carbon. cementite contains 6.67% of 'C', pearlite contains 0.8% carbon. determine pearlite contains how much amount of cementite.

Soln



$$\alpha + \text{Fe}_3\text{C} = 0.8 \text{ C}$$

$$\begin{aligned} \text{amount of cement} &= \frac{CF}{CD} \times 100 \\ &= \left(\frac{0.8}{6.67}\right) \times 100 \end{aligned}$$

Ques
⇒ The fraction of vacancy sites in a metal is 1×10^{-10} at 500°C
Find out the fraction of sites at 1000°C

$$T_1 = 500 + 273 = 773$$

Soln

$$\frac{n_v}{n_t} = e^{-\frac{E}{kT}}$$

$$\Rightarrow \ln\left(\frac{n_v}{n_t}\right) = -\left(\frac{E}{kT}\right)$$

$$\ln(1 \times 10^{-10}) = -\left(\frac{E}{k \times 773}\right)$$

$$x = \ln\left(\frac{n_{v_2}}{n_{t_2}}\right) = -\left(\frac{E}{k \times 1273}\right)$$

$$\Rightarrow \frac{x}{\ln(1 \times 10^{-10})} = \frac{-\frac{E}{k \times 1273}}{-\frac{E}{k \times 773}}$$

$$x = \left(\frac{773}{1273}\right) \times$$

$$x = -13.9819$$

$$\log_e\left(\frac{n_{v_2}}{n_{t_2}}\right) = -13.9819$$

$$\boxed{\frac{n_{v_2}}{n_{t_2}} = 8.467 \times 10^{-7}}$$