



Release Notes

Realtek PCIE Wireless LAN Windows Driver v2024.0.10.105

August 2, 2019

Operating System: Windows 10

Major Changes and Issues Fixed:

Description
Add new HW ID PCI\VEN_10EC&DEV_C822&SUBSYS_C8231D2E for Xiaomi RTL8822CE module
No Wi-Fi networks are found when resumed from Modern Standby. (Only reproduced with RTL8822CE module)
0x9F BSOD with very low probability occurred when run S3 endurance test.
WiFi connection dropped when running Restart Stress Test with the connection to a specific AP that support 802.11k (Radio Resource Management)
Skype disconnected and sound occurred serious lag with the connection to a specific AP that support 802.11k (Radio Resource Management)
Resolved a case of 0x133 BSOD that occurred when running 3DMark test.
Modern Standby performance: Resume Time(s) & Suspend Time(s) result cannot meet SPEC
The link of Miracast may be disconnected when playing local video and projecting to another PC.



Realtek Semiconductor Corp.

No. 2, Innovation Road II, Hsinchu Science Park, Hsinchu 300, Taiwan

Tel.: +886-3-578-0211. Fax: +886-3-577-6047

www.realtek.com.tw

