

INFORMATION : FAULT CODE P2084 (ENGINE ECU)*MOUNTING DELPHI*

Engine ECU DELPHI DCM3.5 branch 2	
Fault code	P2084
After sales description of the fault code	Particulate filter upstream gas temperature sensor : Voltage variation outside the tolerance
Description of the diagnostics	Electrical fault in the particle filter upstream temperature sensor
	Variation in the temperature of more than 100 °C per second
Conditions of activation of the diagnostics	Engine running
Conditions of disappearance of the fault	Driving with the engine hot for 5 minutes
Down-grade modes if fault present	Deactivation of the request for regeneration of the particle filter from the diagnostic tool
Switching on of the warning lamp and/or warning message	Warning lamp MIL
Main customer complaints likely	No effects immediately perceptible to the customer
Suspect areas	Particulate filter upstream gas temperature sensor
	Connector
	Electrical harness